

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 14 Nov 2022

Preliminary Advice

Vehicle No : GBK7775U Accident Date : 07/11/2022
Make : TOYOTA HIACE Policy No. :
DMCVSNW00138232101
Assignment Date : 14/11/2022 Excess : S\$1,500.00
Date of Inspection : 14/11/2022 Est. Duration of Repair : 18
Inspection At : DING AUTO PTE LTD (HQ)
176 SIN MING DRIVE #04-06, SIN MING AUTOCARE
SINGAPORE 575721

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,329.49
Revised Amount	:S\$	14,139.57
Check Items (Estimated)	:S\$	7,625.00
Total	:S\$	21,764.57

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	84,000.00
COE / PARF Rebate	:S\$	21,483.00

Salvage Value	:S\$
Margin for Repair	:S\$ 62,517.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.