REF. 45/EQ1220/1361/Tgyz A.S.S. REC:BY: Taulin ASSIGNMENT Veh No: SHA 77878 Yr Regn: 2021, Thy From: Estimated lost OD (TP) INSITE RESIDENESIEVAINVIMV Truck / Trailer or To Inspectehicle No: Make: at Workship m/s insured / Std / Ni / NA T/Radio; Insured / Std / Ni / NA Sp.Reading insured: Eng/No: KM 4 C851 CVL4143/36. Policy No. C/No: Claims No Gen. Cond: Good) Fair / Poor / Burnt Steering: Inorder Jammed / Leaked / Burnt or Sum insued: Excess: (Client's Record) Brake: Inorder / Jammed / Leaked / Burnt or Make of Veh: Modi: Mit / S/Rim / STD A/Rim or Tyre Size: (Policy Condition) Remark: The veh had commenced its BS / DUN / EXNOVA / GY /-FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO / YOKO DT . Westake Bal. or Market Value: Front Rear IDAC Accident Roort Consistent? : Yes or No R/Bal. Consistent? : Yes or No GIA / PR Seen: L/BaL mm Est. Repairs: davs Res .: Yes or No D.O.A. D.O.1. 3 Val.: Yes or No Lum Sum: Survey held at Des. of Damages : Frt / Rear / O/S CA / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: Ms loke The U/C / Chassis frame / Body Structure affected due to collision. Date / Time | Action / Instruction Taufikh finalised final fig \$2945.08, 3 days. (Red \$590, 17%) : Preli. Report Days Of Repair: 1)12/01 Typist : Final Report Resurvey No. of Trip: Date/Time, File Return to? Survey Fee:

Add Fee:

Report comer:

Lamo Stom / LB is 75

: Site Insp (\$

: Interview (\$

Tech. invs /\$

Weellend is

Transportation:

Photos

Others

_S+RS, SI

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W) 59 Loyang Drive

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER:

EQ Insurance Company Ltd (HQ)

CTPL

Loke Wei Yieng

Singapore

PARTICULARS OF CL	AIM		
Claim Type: Policy No:	THIRD PARTY	Ref. No: Date of Loss:	11/11/2022
Vehicle Reg. No.:	SHA7787S	Driveable?	
Party At Fault:	UNKNOWN		ord in the Trial exalt.
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	27/07/2021
Vehicle Colour:	BLUE		
Engine No:	G4LEKU422237	Chassis No:	KMHC851CVLU193136
Odometer:	171779 KM		
B 1 4 F			
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING	PTE LTD (LOYANG)	

	Amount
	2,005.08
	0.00
	1,530.00
pi pi	0.00
	0.00
Gross Total (S\$)	3,535.08
+ GST 7.00% (S\$)	247.46
Nett Amount (S\$)	3,782.54
	+ GST 7.00% (S\$)

This claim is handled by: MS. LOKE YY TEL: 62148355

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 11 Nov 2022)

Parts:

192

HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code:

ComfortDelGro Engineering Pte Ltd/SHA7787S/11/11/2022 14:57

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty Pa	art No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT DOOR LH	20.00	0.00	*1,797.20 FL
2	1		*FRT FENDER LH	20.00	0.00 4 +	*588.80 FL
3	1		*FRT FENDER EMBLEM BLUE- DRIVE LH	20.00	ىم 0.00	*26.60 FL
4	1		*FRT DOOR COMFORT LOGO RH	0.00	0.00 and	*75.00 F
F=Fra	nchise part.	. L=ListItemI	Disc.	**************************************		
			Sub Total (S\$)			2,487.60
			- List Item Discount on L Items (S\$)			482.52
			Total Parts (S\$)			2,005.08

ComfortDelGro Engineering Pte Ltd/SHA7787S/11/11/2022 14:57. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars			Amount		
Lab	our Items		22			
1	PANEL BEATING	New	350	750.00		
2	SPRAY PAINTING CHARGE		500	600.00		
3	TUFF KOTE	New	30	60.00		
4	TRANSFER OF DOOR	New	60	120.00		
		Gross Labour Cost (S\$)		1,530.00		

ComfortDelGro Engineering Pte Ltd/SHA7787S/11/11/2022 14:57. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfkin 97495749

'WP' 14/4/12 l 415 pm

p/p Kesus before point

tanfkin l /bharsonn

2-3chiys

LKK Auto Consultants hance notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No magai modification(s) is allowed
- Supplementary near slim ist be resurveyed and is subject to the state of the Insurance Company

insight a sublimonist

· Dispute

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755 Workshoos

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 7687

Page: 1


Team:	ARC Repair TP(CLSO)1	JOB CARD Sales Order: 5212538	JC NO305536316
JSTOMER		REGN NO. SHA7787S	MILEAGE
NIVIO	COMFORT TRANSPORTATION PTE L 7010045	HYUNDAI	FUEL EF
DRESS	NO 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717	MODELIONIQ(G3) 11.	12:00 12:00
L. (R)	65508755 (O)	YR OF MANU 7.2021	TARGET DATE
(P)		CHASSIS CODE KMHC851CVLU193136	COMPLETION DATE/TIME:
SCOUNT O	CARD NO		

JOB DESCRIPTION

Accident Date: 11.11.2022 NATURE: 3P 11.11.2022 '

S/NO

LABOR CODE



ECKED & PASSED OUT BY:				
SERVICE ADVISOR		·	CUSTOMER'S SIGNATURE	
wledgement Slip	,	Exit Pass	*	
: o.: e No.: SHA7787S		Vehicle No.: SHA7787S		
		1 110,111,100		
of Service Advisor	Signature/Date	Name of Service Advisor	Date	
returned to Service Reception upon collection		To be kept by Security Guard		