

C86 / AIS 22011362 / Day 3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / INV
 To inspect Vehicle No: _____
 at Workshop no/s: _____
 of: _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 0
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 3% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNF 41512 Yr Reg: NOV / 2013
 Type: M Car / H Cycle / Bus / Van / Large / Load / Prime Mover /
 Truck / Trailer or

Make: Toyota Athera cc 2362
 Colour: Silver AC: Insured / Std / NI / NA
 Sp. Reading: 128985 TR: Insured / Std / NI / NA
 Eng No: 22 2A2J033497
 C/No: JTEGD214608302408

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / SKIN / STD / Rim or

Type Size: Fr: 215/60 R17
 Rr: 11

BS / DUN / ENOVA / GE / FS / LZA / MEC / CHISH / PR / SONY /
 TONY / YOKO or

Front: _____ Rear: _____
 RUB: _____ RUB: _____
 LUB: _____ LUB: _____
 D.O.A: 07/11/22 D.O.A: 18/11/22
 Survey held at: _____ Desk Top

Des. of Damages: Fr / Rear / BS / MS / UC / Roofing or
 Rust

The UC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Alien 2 OD
	WV 47K
	WV 37K
	HL 10K
07/06/23	from 2/5 4:00 - with 4 days from (Red, 3219.60, 459.0)

Date/Time, File Pass to? ☐ Preft. Report
☐ Final Report

Date/Time, File Return to?

Days Of Repair: 4
 Resurvey No. of Trip: _____

Report Format: _____
 Lump Sum / L.B.J: (\$ _____)

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Ins (\$)
☐ Weekend (\$)

Survey Fee:	
Transportation	
Site Insp	
Interview	
Tech. Ins	
Weekend	
TOTAL	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	700G

Vehicle Details

Vehicle No.:	SNF4151Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Nov 2022
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD MR CVT
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	2AZJ033497
Chassis No.:	JTEGD21H608302408
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$47,807.00
Original Registration Date:	13 Nov 2013
First Registration Date:	13 Nov 2013
Transfer Count:	1
Actual ARF Paid:	\$58,930.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Nov 2023
PARF Rebate Amount:	\$29,465.00

Intended COE Rebate Details

COE Expiry Date:	12 Nov 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$77,100.00
COE Rebate Amount:	\$7,593.00
Total Rebate Amount:	\$37,058.00

The information contained herein is correct as at 18 Nov 2022

OK

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001987245	Date of Loss:	07/11/2022
Vehicle Reg. No.:	SNF4151Z	Driveable?	
Driver Age/Info:	41 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SHREE KARTHIGESAN	Contact No:	+6592381093
Driver:	SHREE KARTHIGESAN		
Make/Model:	TOYOTA ALPHARD, 2.4 (A)	Vehicle Reg. Date:	13/11/2013
Vehicle Colour:	Silver		
Engine No:	2AZJ033497	Chassis No:	JTEGD21H608302408
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9		
Description of Accident/Loss	REFER TO GIA REPORT		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	5,275.40
Miscellaneous Items	0.00
Labour	1,880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,155.40
+ GST 7.00% (\$\$)	500.88
Nett Amount (\$\$)	7,656.28

This claim is handled by: **JANICE CHANG SIEW YIN**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

7,19.60

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Nov 2022)
Parts: M1-MPV TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SNF4151Z/11/11/2022 14:34
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>Crack</i>	0	0.00	SH *35.00 FS ✓
2	1		*FRT BUMPER <i>distorted</i>	0.00	0.00	*220.00 F ✓
3	10		*FRT BUMPER CLIP <i>new</i>	0.00	0.00	*10.00 F ✓
4	1		*FRT BUMPER LOWER GRILLE <i>new</i>	0.00	0.00	*90.00 F X
5	2		*FRT BUMPER RETAINER <i>new</i>	0.00	0.00	*90.00 F X
6	1		*FRT BUMPER REINFORCEMENT <i>Reinforced</i>	0.00	0.00	*180.00 F ✓
7	1		*FRT BUMPER SPONGE <i>2 turn</i>	0.00	0.00	*70.00 F ✓
8	1		*FRT BUMPER CHROME <i>2 new</i>	0.00	0.00	*120.00 F 2X
9	1		*FRT PARKING SENSOR (RH) <i>Down</i>	0.00	0.00	*160.00 F ✓
10	1		*FRT GRILLE <i>2 Crack</i>	0.00	0.00	*240.00 F 2L
11	1		*FRT GRILLE EMBLEM <i>2 new</i>	0.00	0.00	*70.00 F ✓
12	1		*FRT BONNET <i>bt</i>	0.00	0.00	*240.00 F ✓
13	2		*FRT BONNET HINGE <i>1/2</i>	0.00	0.00	*90.00 F ✓
14	1		*FRT BONNET CHROME <i>new</i>	0.00	0.00	*180.00 F X
15	9		*FRT BONNET INSULATOR CLIPS <i>new</i>	0.00	0.00	*9.00 F X
16	1		*FRT HEADLAMP(RH) <i>2 money broken</i>	0.00	0.00	*580.00 F 2L
17	1		*FRT FENDER(RH) <i>new</i>	0.00	0.00	*320.00 F X
18	1		*FRT FENDER INNERSHIELD(BH) LH <i>turn</i>	0.00	0.00	*140.00 F ✓
19	10		*FRT FENDER INNERSHIELD CLIP LH <i>new</i>	0.00	0.00	*10.00 F ✓
20	1		*FRT SUPPORT PANEL <i>new</i>	0.00	0.00	*580.00 F X
21	1		*FRT BRACE PANEL <i>1/2</i>	0.00	0.00	*70.00 F 2L
22	1		*AIRCON CONDENSER <i>2 Purified</i>	0.00	0.00	*550.00 F 2L
23	1		*RADIATOR <i>2 Purified</i>	0.00	0.00	*580.00 F 2L
24	1		*RADIATOR AIR GUIDE (RH) <i>1/2 broken</i>	0.00	0.00	*150.00 F X
25	1		*RADIATOR TOP BRACKET <i>2 new</i>	0.00	0.00	*15.00 F 2X

F=Franchise part. S=SpcNett.

Sub Total (S\$) 4,799.00
 + Margin on L,N Items 10.00% (S\$) 476.40
 Total Parts (S\$) 5,275.40

Sng Ah Tee Motor & Panel Service Pte Ltd/SNF4151Z/11/11/2022 14:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

*** Supplementary List.*

- ① FRT Parking sensor Ring Cap - \$10. 1/2 (2nd) ✓
- ② Coolant - \$40. New ✓ SH
- ③ FRT Bumper Tow cover RH - \$12 distorted ✓

Parts 3290.00
 + 1073 3619.00
 Supp 22.00
 + 1073 24.20
 SH 75.00

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	New	850.00 600/-
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New	900.00 600/-
3	TO REFILL AIRCON GAS	New	100.00 80/-
4	TO CHECK WIRING	New	30.00 20/-
Gross Labour Cost (\$)			1,880.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SNF4151Z/11/11/2022 14:34. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5018.20

4/s 4,000/-

18/11/2022

L/Sum.

Not Authorised.

LKK Auto.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: