

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.
Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 24 Nov 2022

Preliminary Advice

Vehicle No	: SNF4151Z	Accident Date	: 07/11/2022
Make	: TOYOTA ALPHARD	Policy No.	: SP2001987245
Assignment Date	: 11/11/2022	Excess	: S\$0.00
Date of Inspection	: DESKTOP SURVEY	Est. Duration of Repair	: 4
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 7,155.40	(Estimate \$7,155.40 + Supplementary \$68.20)
Revised Amount	:S\$ 5,099.20	
Check Items (Estimated)	:S\$ 0.00	
Total	:S\$ 5,099.20	

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 47,000.00
COE / PARF Rebate	:S\$ 37,058.00

Salvage Value	:S\$	
Margin for Repair	:S\$	9,942.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on Lump Sum basis.
kindly approve on supplementary.