

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011363/KQY3Q2**Date:** 18/01/2023**REFERENCE**

Insured/Claimant: Cheng Chee Kiow (inestate) Policy No: DMPCSN00039912103

Date of Loss: 05/11/2022

Nature of Claim: OD

Claim No: SNM22D207979/C01/TAYPH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDW5T**
 Make & Model: MERCEDES-BENZ B180, 1.6 (R16 BI) (A) Engine No: 27091030921384
 Reg. Date: 22/08/2016 (Man. Year: 2016) Chassis No: WDD2462422J390155
 Colour: Metallic Maroon Odometer: 45926 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: S\$70,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm
 Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,590.00	6,820.00	3,770.00	35.60
Miscellaneous Items	327.00	327.00	0.00	0.00
Labour	537.60	441.00	96.60	17.97
Paintwork Labour	695.17	678.46	16.71	2.40
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,149.77	8,266.46	3,883.31	31.96
Approved Total (Overridden) (S\$)		6,600.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	12,149.77	6,100.00	6,049.77	49.79
+ GST 7.00/7.00% (S\$)	850.48	427.00	423.48	49.79
Nett Amount (S\$)	13,000.25	6,527.00	6,473.25	49.79

INSPECTION

Date of Assignment: 11/11/2022 Present Location: S & H Motor Pte Ltd (Sin Ming)
 Date Inspected: 14/11/2022 Inspected At: S & H Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #07-02, Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts:	144	MERCEDES-BENZ B180 1.6 (R16 BI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDW5T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		10,590.00 F	*6,820.00 F
F=Franchise part.						
				Total Parts (\$\$)	10,590.00	6,820.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Misc	327.00	327.00
Sub Total (\$\$)			327.00	327.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	695.17	678.46
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	537.60	441.00
Gross Labour Cost (\$\$)			1,232.77	1,119.46

Report was unsubmitted during this print-out.

< END OF ESTIMATES >