



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22011366/Uny3q2 Date: 06/12/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLW 9568G	Veh. Inspected	SLV 3362C
Policy No.	P10525812R01	Coverage (\$)	0.00
Claim No.	C10018577/JM	Excess (\$)	0.00
Assign From	SALIZAWATI HAIZAR	Assign Date	14/11/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA SIENTA HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NHP1707102417	Colour	BLACK
Odometer	70239 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	HABILEAD	6 mm
L/H Front Tyre	185/60 R15	HABILEAD	6 mm
R/H Rear Tyre	185/60 R15	HABILEAD	6 mm
L/H Rear Tyre	185/60 R15	HABILEAD	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/11/2022	Inspection Date	15/11/2022
Survey held at	PROFI AUTOMOTIVE BLK 10 KAKI BUKIT ROAD 2 #01-05 FIRST EAST CENTRE SINGAPORE 417868		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	