

27	FRONT DOOR PILLAR LH (INNER) <i>qis</i>	1	\$ 405.10	\$ 405.10	x.
28	FRONT DOOR SIDE MIRROR LH <i>new</i>	1	\$ 330.00	\$ 330.00	x.
29	FRONT DOOR LH <i>replaced.</i>	1	\$ 1,620.00	\$ 1,620.00	1450.
30	FRONT DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 250.00	\$ 250.00	x
31	FRONT DOOR OUTERSTRIP LH <i>new</i>	1	\$ 145.00	\$ 145.00	x
32	FRONT DOOR HINGE LH	2	\$ 95.00	\$ 190.00	x
33	FRONT DOOR CHECKER LH	1	\$ 160.00	\$ 160.00	x
34	FRONT DOOR WEATHERSTRIP LH	1	\$ 245.60	\$ 245.60	x
35	FRONT DOOR WIRE HOLDER LH	1	\$ 149.70	\$ 149.70	x
36	FRONT DOOR WIREHARDNESS LH	1	\$ 459.70	\$ 459.70	x.

5729.70
4297.27

TOTAL PRICE \$ 13,338.80
LESS 25% \$ 3,334.70
SUB TOTAL PRICE \$ 10,004.10

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
2	CENTRE GRILLE CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	HEADLAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	BONNET SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
5	FRONT CORNER PANEL SEALANT LH <i>new</i>	1	\$ 60.00	\$ 60.00
6	FRONT STEP PANEL GARNISH RH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	FRONT DOOR PILLAR LH (OUTER) SEALANT	1	\$ 80.00	\$ 80.00
8	FRONT DOOR INNER TRIM CLIP (SET)	1	\$ 30.00	\$ 30.00
9	DASHBOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
10	FRONT WHEEL CAP (SET) <i>new</i>	1	\$ 450.00	\$ 450.00

front door company sticker
new

TOTAL \$ 870.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	800.
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	500.
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK ON SIDE WIREDHARNES	\$ 100.00	30
5	TO REPAIR FRONT CHASSIS MEMBER	\$ 250.00	x
6	REFOCUS HEADLAMP BEAM	\$ 60.00	x

120

7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
8	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	60
9	REMOVE & REINSTALL FRONT WINDOW GLASS	\$ 60.00	x
10	REMOVE AND REFIX DASHBOARD	\$ 850.00	x
11	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	x
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

\$5,230.00

1750

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,874.10
TOTAL LABOUR COST : \$ 5,230.00
TOTAL REPAIR COST : \$ 16,104.10

Supplementary 1: 469

Supplementary 2: 310

total: 6646.275

4/s: 5.31k

06 Days.

5.31k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	GY4919J	Date of Request	15.11.2022
Vehicle Model	TOYOTA HIACE	Number of Days to Extend (If any)	
S/N	Part Description	QTY	LIST PRICE
1	FRONT RADIATOR FAN ASSY <i>cruld</i>	1	\$865.30 <i>492</i>
	<i>492</i>		
	SPECIAL NETT <i>369</i>		
2	RADIATOR COOLANT <i>run</i>	1 SET	\$60.00 <i>40</i>
			<i>40</i>
	LABOUR		
3	TO CONDUCT PRESSURE TEST ON RADIATOR	<i>60</i>	\$100.00

60.

Supplementary 1: 469

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	GY4919J	Date of Request	15.11.2022
Vehicle Model	TOYOTA HIACE	Number of Days to Extend (If any)	
LABOUR REQUEST			
S/N			
1	TO REPAIR FRONT CABIN FLOOR PANEL		\$550.00 250
2	TO REMOVE / REFIT INETRIOR UPHOSTERY TO FACILITATE REPAIR		\$200.00

60.

Supplementary 2: 310.