



# 友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

ZVW50615543

7P Serpo

Vera

LKK

DATE: 10/04/2023 OUR REF: UAPL1592  
REPAIR ESTIMATE TO YOUR TOYOTA PRIUS HYBRID NO: SMZ2329Z

1 FRONT L/H FENDER ASSY	\$	1,060.70	X
1 FRONT L/H FENDER INNER SHIELD	\$	236.70	X
8 FRONT L/H FENDER INNER SHIELD CLIPS	\$	44.00	X
1 FRONT R/H FENDER HYBRID EMBLEM	\$	67.70	X
1 FRONT DOOR PILLAR <i>new</i>	\$	418.90	X
1 FRONT L/H DOOR ASSY <i>Distorted</i>	\$	<del>1,435.20</del>	1252
2 FRONT L/H DOOR HINGES <i>new</i>	\$	240.80	X
1 FRONT L/H DOOR CHECKER <i>new</i>	\$	199.40	X
1 FRONT L/H DOOR LOCK <i>new</i>	\$	<del>607.90</del>	425
1 FRONT L/H DOOR CATCH <i>new</i>	\$	57.70	X
1 FRONT LH OUTER HANDLE <i>new</i>	\$	<del>423.20</del>	361
1 FRONT L/H DOOR WEATHERSTRIP <i>lit</i>	\$	250.70	X
1 FRONT L/H DOOR INNER LINING BOARD <i>caused</i>	\$	<del>985.50</del>	755
1 FRONT L/H DOOR GLASS <i>new</i>	\$	898.70	X 684
1 FRONT L/H DOOR GLASS SEAL RUBBER <i>new</i>	\$	112.40	X
1 FRONT L/H DOOR GLASS OUTER MOULDING <i>behind</i>	\$	108.70	X
1 FRONT L/H DOOR RUNNCHANNEL <i>new</i>	\$	88.40	X
1 FRONT L/H DOOR REGULATOR <i>new</i>	\$	287.80	X
1 FRONT L/H DOOR REGULATOR MOTOR <i>new</i>	\$	996.60	X
1 FRONT L/H DOOR REGULATOR MOTOR COVER <i>new</i>	\$	86.40	X
1 FRONT L/H DOOR TOP BLACK STICKER <i>new</i>	\$	96.20	X
1 FRONT L/H DOOR CENTRE COVER GARNISH <i>new</i>	\$	67.20	X
1 FRONT L/H DOOR WIND MIRROR <i>new</i>	\$	<del>1,360.50</del>	1071
1 FRONT L/H DOOR WIND MIRROR COVER <i>new</i>	\$	142.30	X
1 CENTRE PILLAR PANEL <i>new</i>	\$	549.50	X
1 CENTRE OUTER LOWER GARNISH <i>new</i>	\$	688.70	X
1 REAR L/H DOOR ASSY <i>new</i>	\$	<del>1,401.70</del>	1281
1 REAR L/H DOOR HINGES <i>new</i>	\$	240.00	X
1 REAR L/H DOOR CHECKER <i>new</i>	\$	199.40	X
1 REAR L/H DOOR OUTER HANDLE <i>new</i>	\$	423.20	X
1 REAR L/H DOOR CENTRE RUBBER <i>new</i>	\$	317.10	X
1 REAR L/H DOOR WEATHERSTRIP <i>new</i>	\$	221.60	X
1 REAR L/H DOOR LOCK <i>new</i>	\$	607.90	X
	\$	14,922.70	
LESS 25%.....	\$	3,730.68	
	\$	<u>11,192.03</u>	

**SPECIAL NETT:**

1 SOLAR PAPER FOR DOOR GLASS *new* \$ 100.00 X.

**LABOUR CHARGES:-**

TO TOW THE VEHICLE TO WORKSHOP	\$	60.00	✓
TO DISM/REFIT ROOF LINING, SEAT, PANEL LINING.	\$	200.00	60
TO SPRAY UNDERCOATING IN REPAIR	\$	<del>220.00</del>	50
TO SEND VEHICLE FOR FRONT /REAR COMPUTER ALIGHTMENT	\$	480.00	X
TO DISM/REWIRE DAMAGED PORTION	\$	280.00	30
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	\$	1,300.00	700
TO PUTTY AND RESPRAY DAMAGED PORTION	\$	1,200.00	800
	\$	<u>14,732.03</u>	

- LKK Auto Care Pte Ltd is hereby notified the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged parts during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5810

Total: 7276.92  
4/5: 5.8  
06 days