

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0984/2022/EQ
DATE : 10-Nov-22
WIP : 49486

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LOH TECK KWANG
ADDRESS : BLK 83 WEST COAST DRIVE
#01-07
SINGAPORE 127999
TELEPHONE : HP +65 91818855
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220077874
VEHICLE NO : **SFM 898 L**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 13/7/2022
ENGINE NO : DEM 032217
CHASSIS NO : WAUZZZF5XMA048350
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Nov-22
PLACE OF ACCIDENT : HOLLAND ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFM 898 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X.
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,500.00	500
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.	\$ 3,000.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,522.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFM 898 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>del d</i>	1	\$ 2,493.00	✓	
2	FRONT BUMPER SECURING STRIP - LH / RH <i>new</i>	2	\$ 79.00	+	
3	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 219.00	+	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 293.00	+	
5	FRONT BUMPER AIR GUIDE - LH <i>new</i>	1	\$ 72.00	+	
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	+	
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 151.00	+	
8	FRONT BUMPER OUTER GRILLE HOLE COVER - LH <i>new</i>	1	\$ 54.00	+	
9	FRONT BUMPER TRIM - CENTER <i>new</i>	1	\$ 127.00	+	
10	RADIATOR GRILLE <i>del d</i>	1	TBC	✓	
11	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 141.00	+	
12	RADIATOR GRILLE BRACKET ?	1	\$ 19.00	?	
13	RADIATOR SECURING PLATE ?	1	\$ 12.00	?	
14	FRONT "360" CAMERA ?	1	\$ 1,264.00	?	
15	FRONT BUMPER FOAM FILLER PIECE <i>del d</i>	1	\$ 163.00	✓	
16	FRONT BUMPER REINFORCEMENT BEAM <i>del d</i>	1	\$ 899.00	✓	
17	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 41.00	+	
18	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 143.00	+	
19	CAUTION SIGN STICKER <i>new</i>	1	\$ 16.00	+	
20	AIR CONDITIONER STICKER <i>new</i>	1	\$ 9.00	+	
SUB TOTAL SPARE PARTS			\$ 6,488.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFM 898 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	LOCK CARRIER BRACKET <i>and 2</i>	1	\$ 154.00	✓	
22	FRONT BUMPER SUPPORT - LH / RH ?	2	\$ 64.00	?	
23	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 531.00	+	
24	FRONT PARKING AID SEAL RING {	4	\$ 10.00	+	
25	FRONT PARKING AID SEAL RING { <i>new</i>	4	\$ 16.00	+	
27	FRONT PARKING AID SEAL RING {	4	\$ 10.00	+	
28	HORN HIGH TONE - LH { <i>new</i>	1	\$ 134.00	+	
29	HORN BRACKET - LH	1	\$ 33.00	+	
30	BONNET <i>new</i>	1	\$ 3,491.00	+	
31	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>and</i>	3	\$ 93.00	✓	
32	BONNET STRIKER - LH { <i>new</i>	1	\$ 56.00	+	
33	BONNET LOCK	1	\$ 228.00	+	
34	BONNET BOWDEN CABLE - CENTER {	1	\$ 64.00	+	
35	BONNET RELEASE LEVER { <i>new</i>	1	\$ 15.00	+	
36	BONNET RELEASE CABLE COVER {	1	\$ 11.00	+	
37	BONNET BOWDEN CABLE - CENTER {	1	\$ 64.00	+	
38	HEADLIGHT - LH {	1	\$ 8,172.00	+	
39	LIFT CYLINDER - LH { <i>new</i>	1	\$ 217.00	+	
40	LIFT CYLINDER BRACKET - LH { <i>new</i>	1	\$ 17.00	+	
SUB TOTAL SPARE PARTS		:	\$ 13,380.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFM 898 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	LIFT CYLINDER CORRUGATED PIPE <i>new</i>	1	\$ 107.00	+	
42	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 21.00	✓	
43	RADIATOR AIR GUIDE - LH / RH INNER <i>new</i>	2	\$ 72.00	+	
44	RADIATOR AIR GUIDE - LH / RH OUTER <i>new</i>	2	\$ 38.00	+	
45	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 44.00	+	
46	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 299.00	+	
47	FRONT WHEEL SPOILER - LH <i>new</i>	1	\$ 82.00	+	
48	FRONT NO PLATE <i>new</i>	S/N	\$ 150.00	+ <i>Permy??</i>	
49	SUNDRIES <i>?</i>		\$ 400.00	?	
TOTAL SPARE PARTS		:	\$ 21,081.00		
TOTAL LABOUR CHARGES		:	\$ 6,522.00		
GRAND TOTAL		:	\$ 27,603.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *11/11/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: