

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFM 898 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 X, \$250 ✓	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,500.00 500 ✓	✓
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.	\$ 3,000.00 550 ✓	✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>6,522.00</u>	

[Handwritten signature]

Car-in

13/12/22

mp: 49486

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Benz.



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFM 898 L

DAMAGED PARTS & PRICES

ATG - Adrian

- 3 days

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>del d</i>	1	\$ 2,493.00	1994.40
2	FRONT BUMPER SECURING STRIP - LH / RH <i>acc</i>	2	\$ 79.00	+
3	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	1	\$ 219.00	174.80 <i>sls.</i>
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>acc</i>	1	\$ 293.00	—
5	FRONT BUMPER AIR GUIDE - LH <i>acc</i>	1	\$ 72.00	+
6	FRONT BUMPER CLOSING ELEMENT <i>crushed</i>	1	\$ 293.00	<i>sls.</i> 234
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>acc</i>	1	\$ 151.00	+
8	FRONT BUMPER OUTER GRILLE HOLE COVER - LH <i>acc</i>	1	\$ 54.00	+
9	FRONT BUMPER TRIM - CENTER <i>acc</i>	1	\$ 127.00	+
10	RADIATOR GRILLE <i>crushed</i>	1	TBC	1504.80
11	RADIATOR GRILLE COVER CAP <i>Damaged</i>	1	\$ 112.40	141.00 <i>3 sls.</i>
12	RADIATOR GRILLE BRACKET <i>del d</i>	1	\$ 14.64	19.00
13	RADIATOR SECURING PLATE ?	1	\$ 12.00	? x nn
14	FRONT "360" CAMERA ?	1	\$ 1,264.00	? x nn
15	FRONT BUMPER FOAM FILLER PIECE <i>del d</i>	1	\$ 163.00	130.40
16	FRONT BUMPER REINFORCEMENT BEAM <i>del d</i>	1	\$ 899.00	719.20
17	FRONT BUMPER GUIDE SECTION - LH <i>acc</i>	1	\$ 41.00	+
18	FRONT BUMPER TOP COVER <i>acc</i>	1	\$ 143.00	+
19	CAUTION SIGN STICKER <i>2 acc</i>	1	\$ 16.00	+
20	AIR CONDITIONER STICKER	1	\$ 9.00	+
SUB TOTAL SPARE PARTS			\$ 6,488.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFM 898 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LOCK CARRIER BRACKET <i>encl 2</i>	1	\$ 154.00	✓ 122.80
(22)	FRONT BUMPER SUPPORT (LH) RH <i>2H Bnd</i>	2	\$ 64.00	<i>32 pps.</i> 25.60
23	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 531.00	+
24	FRONT PARKING AID SEAL RING <i>2</i>	4	\$ 10.00	+
25	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 16.00	+
27	FRONT PARKING AID SEAL RING	4	\$ 10.00	+
28	HORN HIGH TONE - LH <i>new</i>	1	\$ 134.00	x
29	HORN BRACKET - LH	1	\$ 33.00	x
30	BONNET <i>new</i>	1	\$ 3,491.00	x
31	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Bnd</i>	3	\$ 93.00	✓ 24.24
32	BONNET STRIKER - LH <i>new</i>	1	\$ 56.00	+
33	BONNET LOCK	1	\$ 228.00	+
34	BONNET BOWDEN CABLE - CENTER <i>2</i>	1	\$ 64.00	+
35	BONNET RELEASE LEVER <i>new</i>	1	\$ 15.00	+
36	BONNET RELEASE CABLE COVER	1	\$ 11.00	+
37	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	+
(38)	HEADLIGHT - LH <i>encl 2</i>	1	\$ 8,172.00	<i>pps.</i> 6537.60
39	LIFT CYLINDER - LH <i>new</i>	1	\$ 217.00	+
40	LIFT CYLINDER BRACKET - LH <i>new</i>	1	\$ 17.00	+
SUB TOTAL SPARE PARTS			\$ 13,380.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFM 898 L

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
41	LIFT CYLINDER CORRUGATED PIPE <i>not in</i>	1	\$	107.00	<i>+</i>	
42	OUTSIDE TEMPERATURE SENSOR BRACKET <i>not in</i>	1	\$	21.00	<i>✓</i>	16.32
43	RADIATOR AIR GUIDE (LH) / RH INNER <i>LH could</i>	2	\$	72.00	<i>+</i>	36.28.40
44	RADIATOR AIR GUIDE - LH / RH OUTER <i>not in</i>	2	\$	38.00	<i>+</i>	
45	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$	44.00	<i>+</i>	
46	FRONT WHEEL HOUSING LINER - LH <i>not in</i>	1	\$	299.00	<i>+</i>	
47	FRONT WHEEL SPOILER - LH <i>not in</i>	1	\$	82.00	<i>+</i>	
48	FRONT NO PLATE <i>not in</i> (by owner)	S/N	\$	150.00	<i>+</i>	80 Parking??
49	SUNDRIES <i>by ?</i> nec		\$	400.00	<i>+</i>	4.96
TOTAL SPARE PARTS			:	\$	21,081.00	
TOTAL LABOUR CHARGES			:	\$	6,522.00	
GRAND TOTAL			:	\$	27,603.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.