

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
TAX Number: 63685162	
Estimator Telephone Number: 63685503	
Accident Reporting Number: 69862672	

Date Generated : 15/12/2022
User ID : PohSuan

Section A - Accident Details

Registration Number	SHF2T
Case Reference Number	TAX/11/22/2015
Registration Date	3/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TEO YI HAO REMUS
Type of Accident	Side Swipe
Accident Date and Time	9/11/2022 10:05 PM
Accident Reported Date and Time	10/11/2022 1:07 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116839
Special Instruction to ARC, if any	TP/ RIGHT REAR PORTION/ INCOME - LKK
Prepared Date and Time	11/11/2022 3:06 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$500.00
Total Spray Cost	\$1,854.00	\$900.00
Total Spare Part Cost	\$5,963.82	\$2,478.01
Total Other Cost	\$920.00	(\$628.01)
TOTAL COST	\$9,582.82	\$3,250.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Boon Chew Tay	GuoQiang (LKK) / NTUC
ARC / Surveyor Sign Off Date	14/11/2022 9:54 AM	11/11/2022 5:40 PM
Signature		
Remarks	LUMPSUM REPAIR / AFTER PAINT PHOTO FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR guoqiang (LKK) & Email guoqiang@lkkauto.com HP: 82880282	

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E 4, Singapore 757705
TAX Number: 63885562
Estimator Telephone Number: 69662623
Accident Reporting Number: 69662672

Date Generated: 15/12/2022
User ID: PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0028	Invoice Number	
Quotation Date	07.12.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$845.00	\$500.00
Total Labour	\$845.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$100.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$100.00
RESPRAY WHEEL CAP	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,854.00	\$900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$798.01)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE	\$120.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
Total Other Costs	\$920.00	(\$628.01)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.18	Replace	Replace
		5246247030	PAD, RR BUMPER, RH & LH	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5246247020	PAD, RR BUMPER, RH & LH	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5246247010	PAD, RR BUMPER, RH & LH	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5219147030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace	Replace

✓ DEF
✓ NEC
✓ NEC
✓ NEC
✓ NEC

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4 Singapore 757705
FAX Number 63685502
Estimator Telephone Number 69662023
Accident Reporting Number 63662672

Date Generated 15/12/2022
User ID : PohSuan

52575470 40	RETAINER RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace	Replace	✓ NEC
52591470 50	SEAL RR BUMPER, RH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given	X NN
52161160 10	CLIPS PIECE FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	✓ NEC
52453470 10	GUARD RR BUMPER LOWER	1.00	\$623.50	25.00	\$467.63	Replace	Replace	✓ DEF
52169470 20	COVER GUARD RR BUMPER LOWER	0.00	\$16.70	0.00	\$0.00	Replace	Not Given	X NN
52461470 10	PAD RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	Replace	✓ NEC
52565479 00	FILLER RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace	Replace	✓ NEC
81551472 81	LENS & BODY REAR COMBINATION LAMP, RH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X NN
81581470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X NN
58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X NN
61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	100.00	\$0.00	Replace	Repair	R
65637470 60	LINER, REAR FENDER, RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X NN
42611474 50	WHEEL, DISC	1.00	\$2,036.30	100.00	\$0.00	Replace	Repair	R
42602471 80	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace	Replace	✓ CUT
43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Check	X NN
48530807 91	ABSORBER SET, SHOCK, REAR RH & LH	0.00	\$137.50	0.00	\$0.00	Replace	Check	X NN
48770470 10	ARM ASSY, UPPER CONTROL, REAR RH	0.00	\$455.00	0.00	\$0.00	Replace	Check	X NN
75850479 10	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	100.00	\$0.00	Replace	Repair	R
67003472 10	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace	✓ BT
	TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	✓ CUT
Total			\$9,617.34		\$2,478.01			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2,478.01
+ 500.00 L/S \$3,250/-
+ 1070.00
4,048.01
-20%
3,238.41

CONFIRMED LUMP SUM REPAIR \$3,250.00 / 5 REPAIR DAYS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

H42 LKK

H4