

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD7136E

01.10.2022

MAKE 10.11.2016

MODEL HYU- I40

Type CHIANG/ INCOME

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER COVER		\$553.00
10	REAR BUMPER CLIPS	\$2.20	\$22.00
2	REAR BUMPER BRACKET LH/RH	LHX \$35.60	\$71.20
1	REAR BUMPER REFLECTOR LH/RH	\$32.00	\$32.00
	SUB TOTAL		\$678.20
	20.00%	610.60	\$135.64
	DISCOUNTED TOTAL	488.48	\$542.56
1	REAR REVERSE SENSOR		\$135.70
1	REAR BUMPER MAT	50	\$50.00
			\$185.70
	Labour Charge		
	Panel Beating		\$300.00
	Spray Painting Charge		\$300.00
	Remove/refix reverse sensor	560	\$60.00
	Check Lighting & Wiring		\$40.00
	TOTAL LABOUR	1098.48	\$700.00
	ESTIMATE TOTAL	488.48	\$1,428.26
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.		

Tanfui 97495749
 WP' 03/10/22 @ 2440pm
 2 days
 1/5 Resurvey after repair
 Tanfui e/khandi.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: