

AS: S. REC: BY: Tawfik

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
☒	☐

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: Ms. Lake

Veh No: SHA 5730T Yr Regn: 2019 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai C.C. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 643241 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HC 85 / CVK 4141702

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 145/65R15

R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 4/10/22

Survey held at Confort bayani

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. rvs (\$ _____)

☐ : Wash and wax (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI. _____

Photos _____

Others _____

Report Form: _____

Letter to Client: _____

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA5730T

Make : HYUNDAI

Model : IONIQ

Date: 10/03/22

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 459.40
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER CENTRE MOULDING			\$ 451.25
1	REAR BUMPER REFLECTOR LAMP LH			\$ 41.45
1	TAIL LAMP LH			\$ 935.40
1	ASSY BLIND SPOT RADAR LH			\$ 1,625.00
1	REAR BUMPER SIDE BRACKET LH			\$ 55.80
1	REAR WHEEL HUB CAP LH			\$ 346.40
			2270.25	
	SUB TOTAL			\$ 3,936.70
	LESS 20%		1816.20	\$ 787.34
	DISCOUNTED TOTAL			\$ 3,149.36
1	REAR TYRE LH			\$ 216.00 <i>80%</i>
1	REAR FENDER ADVERTISEMENT LOGO LH RH			\$ 200.00
1	REAR FENDER PETROL STICKER			\$ 15.00
			387.80	\$ 431.00
	Labour Charge			
	PANEL BEATING			\$ 350 750.00
	SPRAY PAINTING CHARGE		880	\$ 500 600.00
	CHECK ALL LIGHTING			\$ 30 60.00
	TOTAL LABOUR		3084	\$ 1,410.00
	ESTIMATE TOTAL		4524.50	\$ 4,990.36
			2 days	

Nett 172.80

Nett

Nett

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 97495719
 WP 4/00/12 E 4p
 clb Rong after repair
 Tanji @ the car
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 03.10.2022 16:24

Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4944742


JC No: 305532115

CUSTOMER		REG NO:	MILEAGE
/MS COMFORT TRANSPORTATION PTE LTD		SHA5730T	
STOMER NO 7010045		MAKE:	FUEL
DRESS 383 SIN MING DRIVE		HYUNDAI	E.....1/2.....F
Singapore SINGAPORE 575717		MODEL	DATE/TIME IN
(R) 65508755 (O)		IONIQ(G2)	03.10.2022 13:35
COUNT CARD NO.		YR OF MANU.	TARGET DATE
		18.04.2019	
		CHASSIS CODE	COMPLETION DATE/TIME:
		KMHC851CVKU141702	

Accident Date: 03.10.2022
ATURE: 3P 03.10.2022

JOB DESCRIPTION

NO	LABOR CODE	DESCRIPTION
----	------------	-------------



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHA5730T YY

Vehicle No.: SHA5730T

of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard