

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB3755E

Make : HYUNDAI

Model : IONIQ(G3)

Date: 04.10.2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			✓ \$459.40 <i>over</i>
10	REAR BUMPER CLIPS			✓ \$22.00 <i>per</i>
1	REAR BUMPER CENTRE MOULDING ASSY			✓ \$451.25 <i>de</i>
1	REAR BUMPER REINFORCEMENT			\$394.80 <i>Run</i>
1	REAR BUMPER REINFORCEMENT BRACKET LH			\$138.10 <i>Run</i>
1	REAR BUMPER SIDE BRACKET LH			✓ \$55.80 <i>de</i>
1	BOOTLID			\$2,549.70 <i>RP</i>
1	BOOTLID HYUNDAI PLATE			✓ \$24.30 <i>per</i>
1	EMBLEM HYBRID			✓ \$24.30 <i>de</i>
1	EMBLEM - IONIQ			✓ \$31.30 <i>de</i>
1	REAR BUMPER TOWING COVER			✓ \$98.80 <i>de</i>
1	ANTENNA SMARTKEY			\$40.50 <i>Run</i>
1	REAR BUMPER FOG LAMP			\$201.50 <i>Run</i>
1	REAR BUMPER LWR CTR MOULDING			✓ \$155.00 <i>de</i>
1	REAR PANEL GARNISH			\$346.80 <i>Run</i>
		LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		
SUB TOTAL			1297.85	
LESS 20%			1038.28	\$4,993.55
DISCOUNTED TOTAL				\$998.71
				\$3,994.84
REAR NUMBER PLATE WITH TRIM COVER				✓ \$55.00 <i>Run</i>
RENEW ADVERTISEMENT STICKER			SN 350	✓ \$350.00 <i>per</i>
BOOTLID COMFORT TEL NO STICKER			335	✓ \$40.00 <i>per</i>
BOOTLID COMFORT LOGO STICKER			10% 301.50	✓ \$30.00 <i>per</i>
BOOTLID COMFORT APP STICKER				✓ \$30.00 <i>per</i>
REAR BUMPER REVERSE SENSOR				✓ \$180.00 <i>Run</i>
			NETT	\$685.00
Labour Charge				
PANEL BEATING				\$800.00 <i>350</i>
SPRAY PAINTING CHARGE				\$600.00 <i>500</i>
CHK ALL LIGHTING				\$60.00 <i>X</i>
TUFF KOTE				\$60.00 <i>X</i>
REMOVE/REFIX REVERSE SENSOR			880	\$80.00 <i>30</i>
TOTAL LABOUR			\$2569.78	\$1,600.00
ESTIMATE TOTAL			02 days	\$6,279.84

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

p/p Runy before paint

10/3/22, 2:20 PM

Repairer Estimate

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6260 Facsimile + 65 6280 9755

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508959
383 Sin Ming Drive Singapore 575717

Date/Time: 04.10.2022 12:39

Page : 1

Job: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4944814


JC N305532126

CUSTOMER VMS CITYCAB PTE LTD CUSTOMER NO. 7010070 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65551188 (O) (P) ACCOUNT CARD NO.	REGN NO.: SHB3755E	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3)	DATE/TIME IN 04.10.2022 10:05
	YR OF MANU. 30.10.2020	TARGET DATE
	CHASSIS CODE KMHC851CVLU184601	COMPLETION DATE/TIME:

Accident Date: 03.10.2022
 ATURE: 3P 03.10.2022

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

e No.: SHB3755E

YY

Vehicle No.:

SHB3755E

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard