

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB3755E

Make : HYUNDAI

Model : IONIQ(G3)

Date: 04.10.2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH			\$138.10
1	REAR BUMPER SIDE BRACKET LH			\$55.80
1	BOOTLID			\$2,549.70
1	BOOTLID HYUNDAI PLATE			\$24.30
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	REAR BUMPER TOWING COVER			\$98.80
1	ANTENNA SMARTKEY			\$40.50
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR BUMPER LWR CTR MOULDING			\$155.00
1	REAR PANEL GARNISH			\$346.80
		LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		
SUB TOTAL			1297.85	\$4,993.55
LESS 20%			1038.28	\$998.71
DISCOUNTED TOTAL				\$3,994.84
REAR NUMBER PLATE WITH TRIM COVER				\$55.00
RENEW ADVERTISEMENT STICKER			SN 350	\$350.00
BOOTLID COMFORT TEL NO STICKER			335	\$40.00
BOOTLID COMFORT LOGO STICKER			10% 301.50	\$30.00
BOOTLID COMFORT APP STICKER				\$30.00
REAR BUMPER REVERSE SENSOR				\$180.00
		NETT		\$685.00
Labour Charge				
PANEL BEATING				\$800.00
SPRAY PAINTING CHARGE				\$600.00
CHK ALL LIGHTING				\$60.00
TUFF KOTE				\$60.00
REMOVE/REFIX REVERSE SENSOR			880	\$80.00
TOTAL LABOUR			\$2569.78	\$1,600.00
ESTIMATE TOTAL			02 days	\$6,279.84

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

p/p survey before paint