

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22011388/TWY3Q2**Date:** 28/12/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000213		
Claimant Vehicle No :	SHD7314H	Insured Vehicle No :	SLE9204B		
Date of Loss:	11/11/2022	Nature of Claim:	TP	Claim No:	M2206361

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD7314H	Engine No:	G4LEJU132632
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU122044
Reg. Date:	04/12/2018 (Man. Year: 2018)	Odometer:	419515 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Excellent	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,843.72	1,271.92	2,571.80	66.91
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,700.00	990.00	710.00	41.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,554.72	2,272.92	3,281.80	59.08
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	5,554.72	1,800.00	3,754.72	67.60
+ GST 7.00/7.00% (S\$)	388.83	126.00	262.83	67.60
Nett Amount (S\$)	5,943.55	1,926.00	4,017.55	67.60

INSPECTION

Date of Assignment:	14/11/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	14/11/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Dec 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD7314H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	481.10 FL	*481.10 FL
2	1		*FRT BUMPER UPPER MOULDING	Not Necessary	368.50 FL	*- FL
3	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*FRT FENDER RH	Bent	588.80 FL	*588.80 FL
5	1		*FRT FENDER BLUE-DRIVE RH	Necessary	26.60 FL	*26.60 FL
6	1		*FRT WHEEL CAP RH	Cut	346.40 FL	*346.40 FL
7	1		*HEADLAMP RH	Not Necessary	2,110.30 FL	*- FL
8	1		*DAYLIGHT RH	Not Necessary	642.50 FL	*- FL
9	1		*DAYLIGHT GRILLE RH	Not Necessary	93.45 FL	*- FL
10	1		*FRT FENDER ADVERTISEMENT STICKER RH	Necessary	100.00 F	*100.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,779.65	1,564.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	935.93	292.98
Total Parts (\$\$)	3,843.72	1,271.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING	New	700.00	500.00
3	TUFF KOTE	New	40.00	30.00
4	CHECK LIGHTINGS	New	40.00	30.00
5	WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$\$)			1,700.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >