

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Wan Cong

Date: 27 Dec 2022

Preliminary Advice

Insured Vehicle No	: SLE9204B	Accident Date	: 11/11/2022
TP Vehicle No	: SHD7314H	Assignment Date	: 14/11/2022
Make	: HYUNDAI IONIQ HYBRID	Est. Duration of Repair	: 2 DAYS
Date of Inspection	: 14/04/2022		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,554.72
Revised Amount	:S\$	2,272.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,272.92
 Lump Sum Repair	 :S\$	 1,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.