

WIN AUTOMOVITIVE SERVICES
SNH 1988K MERCEDES B180

Estimate - Parts(s)

S/N Qty Descriptions

Amount

LIST ITEMS:-

1	1	rear bumper	1700 de ✓ 1404
2	2	rear bumper side retainer	180 K un
3	1set	rear bumper fasteners	20 un ✓
4	1	rear bumper reinforcement	580 ? bt ✓ 432
5	1	rear bumper lower diffuser	280 de ✓
6	1	rear bumper lower diifuser chrome moudling	240 un ✓ 155.40
7	1	rear bumper towing cover	95 un ✓
8	1	rear bumper inner center frame	298 K un
10	1	rear bumper inner switch sensor module bracket	355 K un
11	1	bootlid	2300 bt ✓ 1800
12	1	bootlid inner lock	320 ? bt ✓ 298.70
13	1	bootlid lower inner trim	285 K un
	1	bootlid top inner trim	395 K un
14	1	bootlid inner trim fasteners	30 K un
15	1	bootlid weatherstrip	250 ? twi ✓ 220
16	1	bootlid chrome moulding	290 un ✓
17	1	bootlid logo emblem	95 de ✓
18	2	bootlid LH & RH shock absorber	450 K un
19	1	bootlid outer lock handle accurator	480 K un
20	2	bootlid lamp LH & RH each 475	1150 ? 950 un ✓
21	1	B180 emblem	90 un ✓
22	2	taillamp LH & RH assy	1250 K un ✓
23	1	taillamp LH & RH lower bracket holder	250 K ✓
24	1	rear windscreen	850 X } un
25	1	rear windscreen wiper assy	460 X }
26	1	rear end panel	1380 R ✓
27	1	rear end panel top garnish	165 ? de ✓
28	1	rear end panel top garnish fasteners	30 ? 20 un ✓
29	2	rear fender LH & RH inner trim board	1180 K un
30	2set	rear fender LH & RH inner trim board fasteners	85 K un

Less 10%

15533 6220.10
1553.3 5598.09
13979.7

Special Nett Item

1	rear end panel sealant	80 402 un
2	rear windscreen sealant	80 60 un
3	reverse sensor	200 un

4	reverse camera	300 200 700
5	rear car plate and housing	40 100 260
TOTAL		700

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
		B/F	
LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts	800 600
2		To check wiring and rewire	60 30
4		to remove and reinstall reverse sensor and reverse camera	120 50.
5		To anti-rust	120 30
6		to remove and reinstall bootlid components	100 60
7		To putty and spray-paint of affected areas	800 700
8		To clear/reset fault code	250/50 700
9		to remove and reinstall rear boot upholstery	100 60
11		to remove and reinstall rear windscreen conduct water test leak	150 120
			2500 1650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfmi 97495749
 Wrt 05/12/22 @ 440pm
 L/s Henry after the repair
 06 days
 Tanfmi @ Lkhants-wu

5598.09
 260
 1650
 7508.09
 4158 6000
 06 days
 ✗