

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 96301007
QUEK DOON KEONG
BLK 60 NEW UPPER CHANGI ROAD
11-1214
SINGAPORE 461060
TEL : FAX :
PH : 96301007
ATTN :

ESTIMATE BILL

Number : EB00006136
Date : 14/11/2022
Case No : AD00013280
Vehicle No : SLH1026K
Chassis : RU11205532
Year of Mfr : 2016
Policy No : 5085133352-06
Model : HONDA VEZEL

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE <i>Body 20</i>	1.0	1,193.10	20	954.48
2	TAILGATE EMBLEM <i>11</i>	1.0	19.30	20	15.44
3	TAILGATE LOGO - VEZEL <i>11</i>	1.0	43.30	20	34.64
4	TAILGATE INNER LOCK <i>11</i>	1.0	96.60	20	77.28
5	REAR BUMPER <i>20</i>	1.0	405.30	20	324.24
6	REVERSE SENSOR <i>Stuck</i>	1.0	411.70	20	329.36
List Price - Parts Sub Total					1,735.44
7	WINDSCREEN SEALANT <i>11</i>	2.0	24.00	0	48.00
8	REAR NUMBER PLATE <i>11</i>	1.0	30.00	0	30.00
9	REAR NUMBER PLATE <i>11</i>	1.0	30.00	0	30.00
10	END PANEL - REPAIR <i>R</i>	1.0			
Special Nett Price - Parts Sub Total					108.00
Parts Total					1,843.44
11	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
12	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
13	ANTI-RUST COATING	1.0	100.00	0	100.00
14	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
15	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,030.00
SINGAPORE DOLLARS : FOUR THOUSAND ONE HUNDRED FORTY-FOUR AND CENTS FIFTY-EIGHT ONLY					
Less Excess					0.00
SUBTOTAL					3,873.44
GST 7.00%					271.14
TOTAL					4,144.58

Date of accident : 10/11/2022 02:30 PM. Place : JOO SENG ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Issued by : Anyasia