


AE/S. REC:BY: Taufik REF: as/CT122011396/Tuyi

ASSIGNMENT

From: _____ Date: _____
 Estimated cost: _____
 OD / TP / VS / TP RES / OD RES / EVA / INV / MV
 To inspect/Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: YQ 8182U
 Policy No. DMCSNW00154782100
 Claims No. SNM22D207644/C02/KHONGLH
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$15K.
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBT4528P. Yr Regn: 2022, Feb
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha Aerox 155 C.C. 155
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: M43566420 M.J015151
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: NI / S/Rim / STD A/Rim or _____
 Tyre Size: F: 110/80R14
 R: 170/70R14
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Maxxis.
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 22/10/2022 D.O.I. 14/11/22
 Survey held at Ergut Lee
 Des. of Damages: FR / Rear O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Limit \$6000
12/5/23	Taufikh confirmed LS \$4900 (Red 9469.22, 65%)

Date/Time, File Pass to? ☐ : Preli. Report
 1) ☐ : Final Report
 Date/Time, File Return to?
 2) 12/5/23-typist
 Rep. Form: Merimen
 Lum Sum: \$4900
 Days Of Repair: 5
 Resurvey No. of Trip: _____
 Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. ins (\$) ☐ : Wash and
 Survey Fee: _____
 Transportation: _____
 S + RS _____
 Photos _____
 Others _____

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 12-Nov-22

Estimate no.

1186

Plate No. FBT4528P

Model. AEROX V2

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 550.00	bt	
2	FORK T-UNDER BRACKET	\$ 200.00	bt	
3	STEERING CONE	\$ 200.00	na	
4	FRONT SPORT RIM	\$ 480.00	?	
5	FRONT TYRES	\$ 150.00	x	
6	FRONT TYRES SHAFT	\$ 120.00	?	
7	FRONT DISC BRAKE	\$ 180.00	?	
8	FRONT CALIPER	\$ 280.00	dd	
9	FRONT ABS PLATE	\$ 100.00	?	
10	FRONT FENDER INNER COVER	\$ 180.00	cr	
11	CAMERA SET	\$ 350.00	dis	
12	HEAD LIGHT SET	\$ 500.00	cr	
13	HEAD LAMP STAY	\$ 280.00	?	
14	ABS PUMP	\$ 1,200.00	?	
15	FRONT SIGNAL LIGHT RIGHT	\$ 180.00	cr	
16	FRONT SIGNAL LEFT	\$ 180.00	x	
17	BODY UNDER COVER	\$ 250.00	de	
18	PRESS BODY	\$ 450.00	?	
19	IGNITION KEY SET	\$ 700.00	?	
20	ECU	\$ 800.00	x	
21	PANEL COVER	\$ 180.00	cr	
22	PANEL INNER COVER	\$ 280.00	dis	
23	HEAD LIGHT PANEL COVER	\$ 120.00	cr	
24	INNER BOX COVER	\$ 200.00	x	
25	FRONT FAIRING INNER COVER RIGHT	\$ 150.00	dis	
26	FRONT FAIRING INNER COVER LEFT	\$ 150.00	x	
27	ALARM SWITCH SENSOR	\$ 100.00	?	
28	HANDLE BAR	\$ 220.00	?	
29	MIRROR SET	\$ 120.00	cr	

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

REG. NO. 201918537M
 EMAIL : enquiry@erzateleemotor.com
 Office : 69661751

ESTIMATE COST OF REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Not Acknowledged by Repairer
 Signature:
 Date:
 Estimate no. 1186

Date: 12-Nov-22

Plate No. FBT4528P
 Model. AEROX V2

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
30	BRAKE LEVER RIGHT	\$ 80.00	X	
31	BRAKE LEVER LEFT	\$ 80.00	bt	
32	MIRROR BRACKET	\$ 100.00	?	
33	HANDLE BAR END	\$ 120.00	ant	
34	HANDLE COVER 1	\$ 150.00	X	
35	HANDLE COVER 2	\$ 100.00	X	
36	IU UNIT	\$ 155.80	ant	
37	IU BRACKET	\$ 50.00	X	
38	WIRE HARNESS SET	\$ 900.00	X	
39	FRONT NUMBER PLATE	\$ 30.00	m/z	
40	FRONT FOOTREST BOARD RIGHT	\$ 250.00	de	
41	FRONT FOOTREST BOARD LEFT	\$ 250.00	?	
42	FRONT FOOTREST UNDER COVER RIGHT	\$ 180.00	dis	
43	FRONT FOOTREST UNDER COVER LEFT	\$ 180.00	dis	
44	MAINSTAND	\$ 400.00	bt	
45	AIR BOX COVER	\$ 180.00	ant	
46	CVT HOUSING COVER	\$ 200.00	?	
47	SIDE COVER INNER LEFT	\$ 150.00	X	
48	SIDE COVER INNER RIGHT	\$ 150.00	?	
49	REAR FENDER REFLECTOR	\$ 120.00	X	
50	REAR BOX	\$ 500.00	ant	
51	RIADIATOR PANEL COVER	\$ 200.00	ant	
52	EXHAUST COVER	\$ 180.00	ant	
53	REAR SWING ARM	\$ 380.00	X	
54	COVERSET SILVER/MATTE	\$ 800.00	as to check price	
55	REAR FOOTREST RIGHT	\$ 150.00	X	
56	ABS CABLE WIRE HANDLE GRIP	\$ 200.00	X	
57	HANDLE GRIP	\$ 80.00	?	
58	LABOUR	\$ 800.00	450	

Tanjiun 97495749 / 62563561
 WP 14/11/22 @ 245pm off day,
 Tanjiun @ lkkauto.com
 - To check part prices
 - To check consistency of accident.

Less 10% \$ 1,596.58
 \$ 15,965.80
 Sub Total : \$ 14,369.22
 GST 7% \$ 1,005.85
 Total: \$ 15,375.07

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

2/3 Reopen after repair.