


AS: S. REC: BY: Tauji REF: as/CT122011396/Tuyi

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$15K.
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBT4528P Yr Regn: 2022, Feb
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Yamaha Aerox 155 c.c. 155
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: M43566420 M+J015131
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: NI / S/Rim / STD A/Rim or _____
Tyre Size: F: 110/80R14
R: 170/70R14
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Maxxis
Front _____ Rear _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. _____ D.O.I. 14/11/22
Survey held at Ergat Lee
Des. of Damages: FR / Rear O/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Limit \$6000

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____
Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fee: _____
Transportation: _____
S + RS \$ _____
Photos _____
Others _____
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. ins (\$ _____)
☐ : Wash and _____

Rep. Form: _____
Lum Sum / B. n. p. _____

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 12-Nov-22

Estimate no.

1186

Plate No. FBT4528P

Model. AEROX V2

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 550.00	bt ✓	
2	FORK T-UNDER BRACKET	\$ 200.00	bt ✓	
3	STEERING CONE	\$ 200.00	na ✓	
4	FRONT SPORT RIM	\$ 480.00	?	
5	FRONT TYRES	\$ 150.00	X	
6	FRONT TYRES SHAFT	\$ 120.00	?	
7	FRONT DISC BRAKE	\$ 180.00	?	
8	FRONT CALIPER	\$ 280.00	dd ✓	
9	FRONT ABS PLATE	\$ 100.00	?	
10	FRONT FENDER INNER COVER	\$ 180.00	cr ✓	
11	CAMERA SET	\$ 350.00	dis ✓	
12	HEAD LIGHT SET	\$ 500.00	cr ✓	
13	HEAD LAMP STAY	\$ 280.00	?	
14	ABS PUMP	\$ 1,200.00	?	
15	FRONT SIGNAL LIGHT RIGHT	\$ 180.00	cr ✓	
16	FRONT SIGNAL LEFT	\$ 180.00	X	
17	BODY UNDER COVER	\$ 250.00	de ✓	
18	PRESS BODY	\$ 450.00	?	
19	IGNITION KEY SET	\$ 700.00	?	
20	ECU	\$ 800.00	X	
21	PANEL COVER	\$ 180.00	cr ✓	
22	PANEL INNER COVER	\$ 280.00	dk ✓	
23	HEAD LIGHT PANEL COVER	\$ 120.00	cr ✓	
24	INNER BOX COVER	\$ 200.00	X	
25	FRONT FAIRING INNER COVER RIGHT	\$ 150.00	dis ✓	
26	FRONT FAIRING INNER COVER LEFT	\$ 150.00	X	
27	ALARM SWITCH SENSOR	\$ 100.00	?	
28	HANDLE BAR	\$ 220.00	?	
29	MIRROR SET	\$ 120.00	cr ✓	

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

REG. NO. 201918537M
 EMAIL : enquiry@erzatleemotor.com
 Office : 69661751

ESTIMATE COST OF REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Signature: _____

Date: _____

1186

Date: 12-Nov-22

Plate No. FBT4528P
 Model. AEROX V2

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
30	BRAKE LEVER RIGHT	\$ 80.00	X	
31	BRAKE LEVER LEFT	\$ 80.00	bt	
32	MIRROR BRACKET	\$ 100.00	?	
33	HANDLE BAR END	\$ 120.00	ant	
34	HANDLE COVER 1	\$ 150.00	X	
35	HANDLE COVER 2	\$ 100.00	X	
36	IU UNIT	\$ 155.80	ant	
37	IU BRACKET	\$ 50.00	X	
38	WIRE HARNESS SET	\$ 900.00	X	
39	FRONT NUMBER PLATE	\$ 30.00	m/z	
40	FRONT FOOTREST BOARD RIGHT	\$ 250.00	de	
41	FRONT FOOTREST BOARD LEFT	\$ 250.00	?	
42	FRONT FOOTREST UNDER COVER RIGHT	\$ 180.00	dis	
43	FRONT FOOTREST UNDER COVER LEFT	\$ 180.00	dis	
44	MAINSTAND	\$ 400.00	bt	
45	AIR BOX COVER	\$ 180.00	ant	
46	CVT HOUSING COVER	\$ 200.00	?	
47	SIDE COVER INNER LEFT	\$ 150.00	X	
48	SIDE COVER INNER RIGHT	\$ 150.00	?	
49	REAR FENDER REFLECTOR	\$ 120.00	X	
50	REAR BOX	\$ 500.00	ant	
51	RIADIATOR PANEL COVER	\$ 200.00	ant	
52	EXHAUST COVER	\$ 180.00	ant	
53	REAR SWING ARM	\$ 380.00	X	
54	COVERSET SILVER/MATTE	\$ 800.00	as - to check price	
55	REAR FOOTREST RIGHT	\$ 150.00	X	
56	ABS CABLE WIRE HANDLE GRIP	\$ 200.00	X	
57	HANDLE GRIP	\$ 80.00	?	
58	LABOUR	\$ 800.00	450	

Tanjin 97495719 / 62563561
 WP 14/11/22 @ 245pm off day,
 Tanjin @ lkkauto.com

Less 10%	\$ 1,596.58
	\$ 15,965.80
Sub Total :	\$ 14,369.22
GST 7%	\$ 1,005.85
Total:	\$ 15,375.07

- To check part prices
 - To check consistency of accident.

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

2/3 Repairing after repair.