

CS 6/18 22011400/Tgy3

Others	10
--------	----



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	P000018824	Date of Loss:	09/11/2022
Vehicle Reg. No.:	YN5075G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MONKEY EXPRESS LLP		
Make/Model:	MITSUBISHI FEB21CR4SDEB, 3.0 D (M)	Vehicle Reg. Date:	16/04/2014
Vehicle Colour:	Light Blue		
Engine No:	4P10B12425	Chassis No:	FEB21EA00346
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	9,133.30
Miscellaneous Items	0.00
Labour	2,150.00
Paintwork Labour	1,200.00
Towing	0.00
Calculated Gross Total (S\$)	12,483.30
- Excess (S\$)	600.00
(S\$)	11,883.30
+ GST 7.00% (S\$)	831.83
Nett Amount (S\$)	12,715.13

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Nov 2022)
 Parts: N/A MITSUBISHI FEB21CR4SDEB 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/YN5075G/14/11/2022 10:54
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN RUBBER	0.00	0.00	*200.00 F ?
2	1		*FRONT WINDSCREEN PILLAR LH	0.00	0.00	*650.00 F R ₂
3	1		*FRONT WIPER PANEL	0.00	0.00	*350.00 F C ₁ ✓
4	1		*FRONT CORNER PANEL LH	0.00	0.00	*280.00 F C ₁ ✓
5	1		*FRONT CORNER PANEL TOP GARNISH LH	0.00	0.00	*40.00 F ?
6	1		*FRONT PANEL	0.00	0.00	*550.00 F bt ✓
7	1		*FRONT GRILLE	0.00	0.00	*550.00 F C ₁ ✓
8	1		*FRONT GRILLE EMBLEM	0.00	0.00	*60.00 F n ₁ ✓
9	1		*FRONT GRILLE CANTER EMBLEM	0.00	0.00	*55.00 F n ₁ ✓
10	1		*FRONT HEADLAMP LH	0.00	0.00	*330.00 F C ₁ ✓
11	1		*FRONT HEADLAMP LOWER RUBBER LH	0.00	0.00	*20.00 F dis ✓
12	1		*FRONT SIDE LAMP LH	0.00	0.00	*125.00 F C ₁ ✓
13	1		*FRONT SIGALLAMP LH	0.00	0.00	*180.00 F C ₁ ✓
14	1		*FRONT BUMPER	0.00	0.00	*550.00 F bt ✓
15	1		*FRONT BUMPER BRACKET LH	0.00	0.00	*58.00 F bt ✓
16	1		*FRONT BUMPER BRACKET INNER LH	0.00	0.00	*65.00 F ?
17	1		*FRONT BUMPER PAD LH	0.00	0.00	*280.00 F de ✓
18	1		*FRONT DOOR LH	0.00	0.00	*850.00 F bt ✓
19	1		*FRONT DOOR HINGE LOWER LH	0.00	0.00	*55.00 F ?
20	1		*FRONT DOOR RUBBER LH	0.00	0.00	*125.00 F ?
21	1		*FRONT STEP GARNISH	0.00	0.00	*250.00 F C ₁ ✓
22	1		*AIR CON CONDENSER <i>dismantle photo</i>	0.00	0.00	*850.00 F bt ✓
23	1		*FRONT CABIN BAR	0.00	0.00	*750.00 F ?
24	1		*FRONT CABIN SEAL RH	0.00	0.00	*125.00 F ?
25	1		*FRONT CABIN SEAL LH	0.00	0.00	*125.00 F ?
26	1		*FRONT CABIN BRACKET LH	0.00	0.00	*480.00 F ?
27	1		*FRONT CABIN MOUNTING LH	0.00	0.00	*350.00 F ?

F=Franchise part.

Sub Total (\$)	8,303.00
+ Margin on L,N Items 10.00% (\$)	830.30
Total Parts (\$)	9,133.30

Kan Fook Sing Motor Workshop/YN5075G/14/11/2022 10:54. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES	New	1,200.00/000
Labour Items			
2	TO CHECK WIRING SYSTEM	New	50.00 30
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	120.00 ? photo.
4	TO REMOVE/REFIT DASHBAORD	New	260.00 180? photo
5	TO REMOVE/REFIT/REFILL AIR CON GAS	New	120.00 100
6	TO REMOVE/REFIT CUSHION, CARPET AND ETC	New	150.00 60
7	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	50.00 ✓
8	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	1,400.00 1000
Gross Labour Cost (S\$)			3,350.00

Kan Fook Sing Motor Workshop/YN5075G/14/11/2022 10:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

taufik 97495749

15/11/22

Not Authorised

Ex: \$600

taufik@lkhauto.com.

08-09 days

1/5 Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: