

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.
Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 15 Nov 2022

Preliminary Advice

Vehicle No	: YN5075G	Accident Date	: 09/11/2022
Make	: MITSUBISHI FEB21CR4SDEB	Policy No.	: P000018824
Assignment Date	: 14/11/2022	Excess	: S\$600.00
Date of Inspection	: DESKTOP SURVEY	Est. Duration of Repair	: 9
Inspection At	: KAN FOOK SING MOTOR WORKSHOP		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,483.30
Revised Amount	:S\$	8,111.80
Check Items (Estimated)	:S\$	2,926.50
Total	:S\$	11,038.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	27,000.00
COE / PARF Rebate	:S\$	1,667.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,333.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.