

# Vin's

Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

Attention To : GREAT AMERICAN  
INSURANCE COMPANY  
3 Temasek Avenue  
#16-01 Centennial Tower  
Singapore 039190

### Claim Details

Case Ref. No. : OD/112022/5759  
Date : 07-11-2022  
Accident Date : 06-11-2022

### Vehicle Details

Make & Model : Toyota HIACE MANUAL  
Chassis No : JTFHT02P100078685  
Registration No : GBC2849R

| S/N | Description                                        | Qty  | Amount (\$\$) |
|-----|----------------------------------------------------|------|---------------|
| 1   | FRONT BONNET <i>bt</i>                             | 1.00 | \$470.00 ✓    |
| 2   | BONNET RH HINGE <i>Xnn</i>                         | 1.00 | \$30.00       |
| 3   | BONNET LH HINGE <i>Xnn</i>                         | 1.00 | \$30.00       |
| 4   | BONNET EMBLEM <i>nn</i>                            | 1.00 | \$40.00 ✓     |
| 5   | BONNET LOCK <i>bt</i>                              | 1.00 | \$60.00 ✓     |
| 6   | RH HEADLAMP <i>cm</i>                              | 1.00 | \$410.00 ✓    |
| 7   | LH HEADLAMP <i>cm</i>                              | 1.00 | \$410.00 ✓    |
| 8   | FRONT GRILLE BASE <i>cm</i>                        | 1.00 | \$80.00 ✓     |
| 9   | FRONT GRILLE <i>cm</i>                             | 1.00 | \$330.00 ✓    |
| 10  | FRONT BUMPER <i>de</i>                             | 1.00 | \$300.00 ✓    |
| 11  | FRONT BUMPER TOP BEAM <i>bt</i>                    | 1.00 | \$110.00 ✓    |
| 12  | FRONT BUMPER REINFORCEMENT <i>bt</i>               | 1.00 | \$250.00 ✓    |
| 13  | FRONT BUMPER CENTER LOWER GRILLE <i>cm</i>         | 1.00 | \$130.00 ✓    |
| 14  | FRONT BUMPER RH SIDE RETAINER <i>Xnn</i>           | 1.00 | \$80.00       |
| 15  | FRONT BUMPER LH SIDE RETAINER <i>Xnn</i>           | 1.00 | \$80.00       |
| 16  | FRONT SUPPORT PANEL <i>bt</i>                      | 1.00 | \$240.00 ✓    |
| 17  | BRACE PANEL <i>bt</i>                              | 1.00 | \$30.00 ✓     |
| 18  | AIRCON CONDENSER <i>bt</i>                         | 1.00 | \$920.00 ✓    |
| 19  | AIRCON CONDENSER FAN MOTOR <i>X</i> ✓ <i>short</i> | 1.00 | \$850.00 ✓    |
| 20  | AIRCON CONDENSER FAN BLADE <i>X</i>                | 1.00 | \$90.00       |
| 21  | AIRCON CONDENSER FAN COWLING <i>X</i> ✓ <i>cm</i>  | 1.00 | \$220.00 ✓    |
| 22  | RADIATOR <i>bt</i>                                 | 1.00 | \$1,400.00 ✓  |
| 23  | RADIATOR FAN MOTOR <i>Xnn</i>                      | 1.00 | \$850.00      |
| 24  | RADIATOR FAN BLADE <i>Xnn</i>                      | 1.00 | \$90.00       |
| 25  | RADIATOR FAN COWLING <i>X</i> ✓ <i>cm</i>          | 1.00 | \$220.00 ✓    |
| 26  | INTER COOLER <i>bt</i>                             | 1.00 | \$940.00 ✓    |
| 27  | INTER COOLER INLET HOSE <i>Xnn</i>                 | 1.00 | \$210.00      |
| 28  | INTER COOLER OUTLET HOSE <i>Xnn</i>                | 1.00 | \$190.00      |
| 29  | INTER COOLER BRACKET <i>Xnn</i>                    | 1.00 | \$120.00      |
| 30  | INTER COOLER AIR DUCT <i>Xnn</i>                   | 1.00 | \$100.00      |

# Vin's

Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

|    |                               |                   |      |                         |
|----|-------------------------------|-------------------|------|-------------------------|
| 31 | SPARE TANK                    | X                 | 1.00 | \$250.00                |
|    |                               |                   |      | \$9,530.00              |
|    |                               | Margin: 10%       |      | \$953.00                |
|    |                               |                   |      | \$10,483.00             |
| 32 | FRONT NO. PLATE               | bt                | 1.00 | <del>\$40.00</del> 35   |
| 33 | COOLANT                       | ~                 | 1.00 | <del>\$80.00</del> 50   |
| 34 | COMPANY STICKER               | ~                 | 1.00 | <del>\$500.00</del> 200 |
| 35 | TO REFILL AIRCON GAS          |                   | 1.00 | <del>\$150.00</del> 100 |
| 36 | TO REMOVE AND REFIX DASHBOARD |                   | 1.00 | <del>\$380.00</del> XAN |
| 37 | TO REPAIR DAMAGES             |                   | 1.00 | <del>\$980.00</del> 700 |
| 38 | TO SPRAY PAINTING             |                   | 1.00 | <del>\$880.00</del> 400 |
|    |                               | Subtotal w/o GST: |      | \$13,493.00             |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Damaged item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Rasmi  
Hp 90010068

6 days

4/5

EXCESS: TBA

REVERT

Resurvey after repair  
14/11/22 P1516

Issued by Raymond Teo

This is a computer-generated document. No signature is required.