



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|---|------------|
| GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190 | | Ref: CS/GAI22011402/Rvy3m4 Date: 15/12/2022 Code: GAI | |
| 1. Policy Particulars :- OWN DAMAGE | | | |
| Insured Veh. | | Veh. Inspected | GBC 2849R |
| Policy No. | MT20211796 | Coverage (\$) | 0.00 |
| Claim No. | CLMOMVC000004260 | Excess (\$) | 600.00 |
| Assign From | SHERY WONG | Assign Date | 14/11/2022 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA HIACE MANUAL | c.c | 2982 |
| Engine No. | HIDDEN | Year of Reg. | 2011 |
| Chassis No. | JTFHT02P100078685 | Colour | WHITE |
| Odometer | 405171 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | FAIR | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195R15C | BRIDGESTONE | 6 mm |
| L/H Front Tyre | 195R15C | BRIDGESTONE | 6 mm |
| R/H Rear Tyre | 195R15C | BRIDGESTONE | 6 mm |
| L/H Rear Tyre | 195R15C | BRIDGESTONE | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 06/11/2022 | Inspection Date | 14/11/2022 |
| Survey held at | VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722 | | |
| 5a. Remarks | | | |
| A) THE MARKET VALUE IS S\$37,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | |