

Vehicle Damage Assessment Report for [XB9639D]

Estimate Created: 18/12/2022 09:05 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 18/12/2022 09:14 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO INSURANCE	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Isuzu	Model	D-Max
Engine Type	1KDFTV		
License Plate Number	XB9639D	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$6500.00 with 6 days for repair

Insurlogic 1 (18/12/2022 09:14)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
FRONT CORNER TOP GARNISH LH		1	1044.00	-25.00 %	783.00
SIGNAL LAMP LH		1	158.00	-25.00 %	118.50
SIGNAL LAMP GARNISH LH		1	318.00	-25.00 %	238.50
CTR GRILLE OUTER GARNISH		1	681.00	-25.00 %	510.75
FRONT BUMPER		1	960.00	-25.00 %	720.00
FOG LAMP GARNISH LH		1	110.00	-25.00 %	82.50
FRONT DOOR LH		1	3200.00	-25.00 %	2,400.00
FRONT DOOR SIGNAL LAMP LH		1	78.00	-25.00 %	58.50
SET UO UPPER GARNISH LH		1	1078.00	-25.00 %	808.50
SET UP LOWER GARNISH METAL PLATE LH		1	190.00	-25.00 %	142.50
FRONT BUMPER SIDE BRACKET LH		1	198.00	-25.00 %	148.50

Parts Subtotal 6,011.25

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
FRONT BUMPER CLIPS		1.0	35.00	0.00 %	35.00
BONNET COMPANY STICKER		1.0	200.00	0.00 %	200.00

Materials Subtotal 235.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	750.00	0.00 %	750.00
ANTI RUST	RnR	40.00	0.00 %	40.00
CHECK WIRING	RnR	40.00	0.00 %	40.00
RNR DOOR MECHNISM	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	1000.00	0.00 %	1,000.00
Labor Rate	S\$ 50 / Hour			
			General Labor Subtotal	910.00
			Paint Labor Subtotal	1,000.00
			Labor Subtotal	1,910.00

Summary

Repair Cost	8,156.25
Discount(20 %)	(1,656.25)
	6,500.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	6,500.00