



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. XB9639D MITSUBISHI FV517JD2RDEB

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front corner top garnish LH <i>cm</i>		1044.00	
1	Headlamp LH <i>X</i> nn		514.00	<i>X</i>
1	Signal lamp LH <i>cm</i>		158.00	
1	Signal lamp garnish LH <i>cm</i>		318.00	
1	Center grille outer garnish <i>cm</i>		681.00	
1	Front bumper <i>bt</i>		960.00	
1	Front bumper inner bracket <i>X</i> nn		400.00	<i>X</i>
1	Fog lamp LH <i>X</i> nn		285.00	<i>X</i>
1	Fog lamp garnish LH <i>cm</i>		110.00	
1	Front door LH <i>tan</i>		3200.00	<i>7817</i>
1	Front door upper hinge LH <i>X</i> nn		189.00	<i>X 25%</i>
1	Front door lower hinge LH <i>7.X</i> nn		189.00	<i>X 5862.75</i>
1	Front door signal lamp LH <i>cm</i>		78.00	
1	Step up upper garnish LH <i>Refer cm</i>		1078.00	
1	Step up lower garnish LH <i>cm X</i> nn		190.00	<i>X</i>
1	Step up lower garnish metal plate LH <i>cm</i>		190.00	
1	Door pillar LH (Repair refer to labour) R		0.00	
1	Bonnet (Repair refer to labour) R		0.00	
Part Items Total:			9584.00	
			-25% -2396.00	
			7188.00	
SPECIAL NETT ITEMS				
1	Front bumper clips <i>cm</i>		35.00	
1	Center grille clips <i>X</i> nn		25.00	<i>X 235</i>
1	Bonnet company sticker <i>cm</i>		400.00	<i>200</i>
SN Items Total:			460.00	
Total Parts			7648.00	



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. XB9639D MITSUBISHI FV517JD2RDEB

Page No. 2


S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	750
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	750 1000
3	To perform anti-rust treatment on affected areas	90.00	40
4	To remove and repair/refit wiring system at accident damaged area and check for all electrical proper function	90.00	40
5	To remove, replace and focus headlamp LH	50.00 X	
6	To remove and refit/replace front door LH fitting, trimmings, garnish, window glass and lock mechanism	150.00	80
Labour Total :		3180.00	
TOTAL (PARTS & LABOUR):		10828.00	1910

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rahul
Hp 9001268
6 days
2/5
21/11/22 @1340
Reg after repair



Page No. 3

[illegible]