

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/01015/2022/EQ
DATE : 16-Nov-22
WIP : 50513

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/11/2022

YOUR INSURED VEH NO : SMY 9238 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR CHUA SWEE TECK
ADDRESS : 124 JALAN SIMPANG BEDOK
SINGAPORE 488232

TELEPHONE : HP +65 96420106
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800071455-04
VEHICLE NO : **SFS 1889 A**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 20/6/2018
ENGINE NO : CHZ 439381
CHASSIS NO : WAUZZZ8V8J1057881
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Nov-22
PLACE OF ACCIDENT : JALAN SULTAN ROAD, BEFORE MINTO ROAD
LEFT-MOST LANE TOWARDS BEACH ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFS 1889 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	
3	TO RESPRAY FRONT BUMPER.	\$ 900.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,502.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 1889 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,432.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 571.00	
5	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 318.00	
6	FRONT BUMPER TRIM COVER - RH	1	\$ 182.00	
7	FRONT WHEEL HOUSING LINER ADAPTER - RH	1	\$ 42.00	
8	RADIATOR GRILLE	1	\$ 1,578.00	
9	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	
10	AIR CONDITIONER STICKER	1	\$ 9.00	
11	CAUTION SIGN STICKER	1	\$ 16.00	
12	RADIATOR AIR GUIDE GRILLE - RH	1	\$ 210.00	
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	
14	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	
15	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 136.00	
16	HORN LOW TONE - RH	1	\$ 213.00	
17	RADIATOR AIR GUIDE - RH	1	\$ 28.00	
18	RADIATOR AIR GUIDE OUTER SEAL - RH	1	\$ 9.00	
19	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 14.00	
20	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	
SUB TOTAL SPARE PARTS		:	\$ 7,421.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFS 1889 A**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT NO PLATE	S/N	\$ 60.00	
22	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 7,881.00	
TOTAL LABOUR CHARGES		:	\$ 2,502.00	
GRAND TOTAL		:	\$ 10,383.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT