

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 Robinson Road #09-01
Singapore 068897

Xiao Tony.

Quotation

DATE : 11.11.2022
VEH NO : SJT216X
MODEL : Toyota Altis
D O A : 09.11.2022
YR REF : YN5075G

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJT216X (TOYOTA ALTIS)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<u>LIST ITEMS</u>			
1	Rear Number Plate Lamp <i>Not Ne</i>	2	110.40 <i>x.</i>
2	Rear Bumper <i>Distorted</i>	1	495.80 <i>-</i>
3	Rear Bumper Side Holder - LH & RH <i>2nd.</i>	2	72.20 <i>-</i>
4	Rear Bumper Reflector - LH & RH <i>RH cancelled</i>	2	145.00 <i>72.50.</i>
5	Rear Bumper Sponge <i>cancel</i>	1	129.50 <i>-</i>
6	Rear Bumper Reinforcement Bar <i>Best</i>	1	117.50 <i>-</i>
7	Rear Bumper Impact Bracket - LH & RH <i>RH Distorted</i>	2	196.20 <i>98.10</i>
8	Rear End Panel <i>Distorted</i>	1	581.40 <i>-</i>
9	Rear End Panel Top Garnish <i>Distorted</i>	1	192.50 <i>-</i>
10	Tail Lamp - LH & RH <i>LH cancelled, RH smashed</i>	2	650.20 <i>-</i>
11	Tail Lamp Panel - LH & RH <i>RH Distorted</i>	2	396.40 <i>198.20.</i>
12	Bootlid <i>Distorted</i>	1	839.40 <i>-</i>
13	Bootlid Lock <i>Jammed</i>	1	189.20 <i>-</i>
14	Bootlid Weatherstripe <i>cut</i>	1	195.50 <i>-</i>
15	Bootlid Hinges <i>Best.</i>	2	160.80 <i>-</i>
16	Bootlid Outer Chrome Moulding <i>cancel</i>	1	274.80 <i>-</i>
17	Bootlid Reflector - LH & RH <i>RH smashed</i>	2	520.40 <i>260.20.</i>
18	Bootlid Inner Trim Board <i>torn</i>	1	288.80 <i>-</i>
19	Toyota Logo	1	58.10 <i>-</i>
20	Corolla Wording	1	56.40 <i>-</i>
21	Altis Wording	1	59.40 <i>-</i>
22	1.6 Emblem	1	54.30 <i>-</i>
23	Rear Fender - LH & RH <i>RH Distorted</i>	2	1,964.80 <i>982.40.</i>
24	Rear Fender Inner Trim Board - LH & RH <i>RH cancelled</i>	2	664.80 <i>332.40.</i>
25	Rear Fender Inner Shield - LH & RH <i>Not Ne</i>	2	192.40 <i>x.</i>
26	Rear Fender Air Vent - LH & RH <i>RH Distorted</i>	2	124.80 <i>62.40.</i>
27	Rear Windscreen <i>cut</i>	1	1,185.10 <i>-</i>
28	Rear Windscreen Moulding <i>Ne</i>	1	89.40 <i>-</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SJT216X (TOYOTA ALTIS)

29	Spare Tyre Panel <i>Distorted</i>	1	845.90 ✓
30	Spare Tyre Panel Top Board <i>to be</i>	1	289.30 ✓
31	Spare Tyre Lock Screw <i>new</i>	1	40.40 ✓
32	Rear Exhaust Pipe	1	723.10 ✓
33	Rear Exhaust Pipe Mounting	1	35.40 ✓
34	Rear Exhaust Pipe Heat Shield <i>new</i>	1	114.50 ✓
35	Rear Exhaust Pipe Gasket	1	32.90 ✓
36	Rear Door - RH <i>Repair</i>	1	1,141.40 ✓
37	Rear Door Lock - RH <i>new</i>	1	385.70 ✓
38	Speaker Panel <i>Repair</i>	1	598.40 ✓
39	Speaker Panel Trim Board <i>new</i>	1	389.50 ✓

9221.20
6915.90 Less 25%

14,602.00

(3,650.50)

10,951.50

S/NETT ITEMS

1	Rear Number Plate <i>Set</i>	1	30.00 ✓
2	Rear Number Plate Holder <i>new</i>	1	30.00 ✓
3	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
4	Reverse Sensor <i>new</i>	1	280.00 <i>200</i>
5	Rear End Panel Top Garnish Clips <i>new</i>	1 set	20.00 ✓
6	Rear End Panel Sealant <i>new</i>	1	60.00 ✓
7	Bootlid Outer Chrome Moulding Clips <i>new</i>	1 set	20.00 ✓
8	Bootlid Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
9	Rear Fender Inner Trim Board Clips <i>new</i>	1 set	60.00 <i>30</i>
10	Rear Fender Inner Shield Clips <i>new</i>	1 set	30.00 ✓
11	Rear Windscreen Sealant <i>new</i>	1	60.00 ✓
12	Rear Windscreen Solar Film <i>new</i>	1	300.00 <i>200</i>
13	Spare Tyre Panel Insulation Pad <i>new</i>	1	280.00 <i>200</i>

Total Parts

\$ 12,181.50

LABOUR CHARGE

1	To knocking & pull out rear portion & renew parts	\$ 2,200.00 <i>1800</i>
2	To putty & spray up paint works	\$ 1,800.00 <i>1600</i>
3	To check wiring	\$ 100.00 <i>30</i>
4	To spray tuff coat	\$ 250.00 <i>120</i>
5	To remove upholstery	\$ 200.00 <i>150</i>
6	To remove reverse sensor	\$ 100.00 <i>50</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SJT216X (TOYOTA ALTIS)

7	To remove rear windscreen	\$	180.00 120
8	To remove fuel tank	\$	150.00 x
9	To transfer rear door fittings	\$	150.00 x
10	To remove rear exhaust pipe	\$	150.00 x
11	To transfer bootlid fittings	\$	150.00 80
Total Labour		\$	5,430.00
Grand Total		\$	17,611.50

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 11775.90
L/S: 9.4K.

12 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: