

Vehicle Damage Assessment Report for [SLJ1110P]

Estimate Created: 14/11/2022 11:27 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 30/06/2023 14:46 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Land Rover	Model	Discovery Sport
Engine Type			
License Plate Number	SLJ1110P	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$9,073.79 WITH 4 WORKING
DAYS.

Insurlogic 4 (30/06/2023 14:46)

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
BADGE REAR DISCO		1.0	193.86	0.00 %	193.86
NAME PLATE SPORT 4HS		1.0	209.79	0.00 %	209.79
BADGE REAR VERY DS		1.0	173.88	0.00 %	173.88
BADGE OVAL REAR RR3		1.0	103.23	0.00 %	103.23
BUMPER -REAR		1.0	1943.01	0.00 %	1,943.01
BUMPER-COVER		1.0	696.96	0.00 %	696.96
BUMPER NUT XF		15.0	5.04	0.00 %	75.60
REINFORCEMENT - BUMP		1.0	712.17	0.00 %	712.17
MOULDING BRACKET		1.0	394.29	0.00 %	394.29

Materials Subtotal 4,502.79

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING	RnR	1950.00	0.00 %	1,950.00
CHECKING WIRING AND LIGHTING.	RnR	621.00	0.00 %	621.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING	Full spray	2000.00	0.00 %	2,000.00

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	2,571.00
		Paint Labor Subtotal	2,000.00
		Labor Subtotal	4,571.00

Summary

Repair Cost	9,073.79
Discount(0 %)	(0.00)
	9,073.79
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	9,073.79