

SERVICE ESTIMATE

87648 - C00001 SL: SERVICE SALES - PC

Ms Ho Pei Pei (He Beibei)
BLK 121 Bukit Batok Central
#10-451

Singapore 650121

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Ms Ho Pei Pei (He Be

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 14/11/2022
WIP No. . : 49689
Veh.In/Out:
*Tel.No. . : Mobile: 97890707
Reg.No. . : SLJ1110P
Reg.date . : 29/11/2016
Mileage ... : 0
Chassis No: SALCA2AG9HH653983

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE RR BUMPER, RR LOWER COVER, REINFORCEMENT, ETC REPAIR TAILGATE	0	3000.00	0		3,000.00	S
800	TO SPRAY TAILGATE, RR BUMPER, RR LOWER COVER, ETC	0	3000.00	0		3,000.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
	BADGE REAR "DISCO" Dm	1.0 EA	215.40			215.40	S
	BADGE REAR "VERY" DS	1.0 EA	193.20			193.20	S
	BADGE OVAL REAR RR3	1.0 EA	114.70			114.70	S
	Name Plate Sport 4HS	1.0 EA	233.10			233.10	S
	BUMPER - REAR	1.0 EA	2158.90			2158.90	S
	BUMPER - COVER	1.0 EA	774.40			774.40	S
	TOW HOOK COVER REAR	1.0 EA	42.60			42.60	S
	BUMPER NUT XF	15.0 EA	5.60			84.00	S
	REINFORCEMENT - BUMP	1.0 EA	791.30			791.30	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SERVICE ESTIMATE

87648 - C00001 SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Ms Ho Pei Pei (He Beibei)
BLK 121 Bukit Batok Central
#10-451

Inv.No. : B&P 0 Page 2
Inv.date. : 14/11/2022
WIP No. : 49689
Veh.In/Out:

Singapore 650121

*Tel.No. : Mobile: 97890707
Reg.No. : SLJ1110P
Reg.date : 29/11/2016
Mileage : 0
Chassis No: SALCA2AG9HH653983

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Ms Ho Pei Pei (He Be

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER PIN EVOQUE <i>? x 1</i>	10.0 EA	3.50			35.00	S
	LH BRACKET - BUMPER <i>? x 1</i>	1.0 EA	151.50			151.50	S
	RH BRACKET - BUMPER <i>? x 1</i>	1.0 EA	151.50			151.50	S
	LH BRACKET - BUMPER <i>? x 1</i>	1.0 EA	228.90			228.90	S
	RH BRACKET - BUMPER <i>? x 1</i>	1.0 EA	228.90			228.90	S
	SENSOR - PARKING AID <i>? x 1</i>	4.0 EA	517.70			2,070.80	S
	LH LAMP - FOG - REAR <i>X 1</i>	1.0 EA	447.90			447.90	S
	RH LAMP - FOG - REAR <i>X 1</i>	1.0 EA	447.90			447.90	S
	LH MOULDING - REAR W <i>X 1</i>	1.0 EA	403.10			403.10	S
	RH MOULDING - REAR W <i>X 1</i>	1.0 EA	403.10			403.10	S

*Supp

MOUDLING BRACKET \$394.29 ✓ NEC

Same
Hp 90010068
4 days
21/11/22 @ 1100
Reg before reg

Labour Total 6,621.00
Parts Total 9,176.20
Package Total 0.00

Gross Total. 15,797.20
Net..... 15,797.20
GST @ 7.0% 1,105.80
Total..... 16,903.00
Paid..... 0.00
Please Pay.. 16,903.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

87648 - C00001 SL: SERVICE SALES - PC

Ms Ho Pei Pei (He Beibei)
 BLK 121 Bukit Batok Central
 #10-451

Singapore 650121

Closed by : Juan Paulo Bongon Ba
 Svc Consultant : ACC
 Remarks : Ms Ho Pei Pei (He Be

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 20/02/2023
 WIP No. . : 49689
 Veh.In/Out: 09/02/2023 15/02/2023
 *Tel.No. . : Mobile: 97890707
 Reg.No. . : SLJ1110P
 Reg.date . : 29/11/2016
 Mileage ... : 126,019
 Chassis No: SALCA2AG9HH653983

Op.No	Description	Mech Qty	Price Disc%	Pkg	Amount G
	* MOULDING BRACKET <i>cm / sup</i>	1.0 EA	438.10 /		438.10 S

			Gross Total.	438.10
Labour Total	0.00	Net.....	438.10	
Parts Total	438.10	GST @ 8.0%	35.05	
Package Total	0.00	Total.....	473.15	
			Paid.....	0.00
			Please Pay..	473.15

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate