

ASS. REC. BY:

REF:

CC4/GRB 22011419/Rpa3

737B

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 1110P

at Workshop m/s WEARNS

of 45, LEAH KEE RD

Insured: GRB

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Remark: The veh had commenced its
repair at the time of inspection.

	
N/S	O/S
	

Bal. or Market Value:	_____	111K
IDAC Accident Rpt:	_____	Consistent?: Yes or No
GIA / PR Seen:	_____	Consistent?: Yes or No
Est. Repairs:	_____ days	Res.: Yes or No
Item Sum:	_____ %	3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Veh No: SLJ 1110P Yr Regn: 2016 / NOV
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: LAND ROVER DISCOVERY SP 2.0 ^{S/R} 1999 C.C.
Colour: GREY A/C: Insured / Std / Nil / NA
Sp. Reading: 12299 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: SALCA 2A69 HH 653 983
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 235/55R19
R: 21

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

Front 6 mm R/Bal. 6 mm
I/Bal. 6 mm
D.O.A. 10/11/22
Survey held at WEARNES
Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

Repair Limit - 45K

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

$$S + RS \rightarrow S$$

) Photos

Others

TOTAL

Add Fee:

: Site Insp (\$

1: Interview (S

1: Tech. Invs (\$

1. Weekend (\$)

SERVICE ESTIMATE

87648 - C00001 SL: SERVICE SALES - PC

Ms Ho Pei Pei (He Beibei)
BLK 121 Bukit Batok Central
#10-451

Singapore 650121

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Ms Ho Pei Pei (He Be

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 14/11/2022
WIP No. . : 49689
Veh.In/Out:
*Tel.No. . : Mobile: 97890707
Reg.No. . : SLJ1110P
Reg.date . : 29/11/2016
Mileage ... : 0
Chassis No: SALCA2AG9HH653983

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE RR BUMPER, RR LOWER COVER, REINFORCEMENT, ETC REPAIR TAILGATE	0	3000.00	0		3,000.00 1750	S
800	X TO SPRAY TAILGATE, RR BUMPER, RR LOWER COVER, ETC	0	3000.00	0	1000	3,000.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
	BADGE REAR "DISCO" Dm	1.0 EA	215.40			215.40	S
	BADGE REAR "VERY" DS	1.0 EA	193.20			193.20	S
	BADGE OVAL REAR RR3	1.0 EA	114.70			114.70	S
	Name Plate Sport 4HS	1.0 EA	233.10			233.10	S
	BUMPER - REAR	1.0 EA	2158.90			2,158.90	S
	BUMPER - COVER	1.0 EA	774.40			774.40	S
	TOW HOOK COVER REAR	1.0 EA	42.60			42.60	S
	BUMPER NUT XF	15.0 EA	5.60			84.00	S
	REINFORCEMENT - BUMP	1.0 EA	791.30			791.30	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SERVICE ESTIMATE

87648 - C00001 SL: SERVICE SALES - PC

Ms Ho Pei Pei (He Beibei)
BLK 121 Bukit Batok Central
#10-451

Singapore 650121

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 14/11/2022

WIP No. . : 49689

Veh.In/Out:

*Tel.No. . : Mobile: 97890707

Reg.No. . : SLJ1110P

Reg.date . : 29/11/2016

Mileage . : 0

Chassis No: SALCA2AG9HH653983

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Ms Ho Pei Pei (He Be

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER PIN EVOQUE ?	10.0 EA	3.50			35.00	S
	LH BRACKET - BUMPER ?	1.0 EA	151.50			151.50	S
	RH BRACKET - BUMPER ?	1.0 EA	151.50			151.50	S
	LH BRACKET - BUMPER ?	1.0 EA	228.90			228.90	S
	RH BRACKET - BUMPER ?	1.0 EA	228.90			228.90	S
	SENSOR - PARKING AID ?	4.0 EA	517.70			2,070.80	S
	LH LAMP - FOG - REAR X	1.0 EA	447.90			447.90	S
	RH LAMP - FOG - REAR X	1.0 EA	447.90			447.90	S
	LH MOULDING - REAR W X	1.0 EA	403.10			403.10	S
	RH MOULDING - REAR W X	1.0 EA	403.10			403.10	S

Pass
Hp 9001w68
4 days
21/11/22 @ 1100
Reg before repair

Labour Total 6,621.00
Parts Total 9,176.20
Package Total 0.00

Gross Total. 15,797.20
Net..... 15,797.20
GST @ 7.0% 1,105.80
Total..... 16,903.00
Paid..... 0.00
Please Pay.. 16,903.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	737B
Vehicle No.:	SLJ1110P
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2022
Vehicle Make:	LAND ROVER
Vehicle Model:	DISCOVERY SPORT 2.0 SI4 HSE 7STR 5/R
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	015073123000204PT
Chassis No.:	SALCA2AG9HH653983
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$50,339.00
Original Registration Date:	29 Nov 2016
First Registration Date:	29 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$62,611.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2026
PARF Rebate Amount:	\$43,827.00

COE Expiry Date:	28 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$21,288.00
Total Rebate Amount:	\$65,115.00

The information contained herein is correct as at 22 Nov 2022

OK

Land Rover Discovery Sport 2.0A Si4 SE 7-Seater

Overview

Financial

Accessories

Similar

Research

Photos

Map



TRILLIUM
AUTOMOBILE

Price \$11,800

Depreciation ① \$20,970 /yr
View models with similar depre

Reg Date 24-Nov-2016
(4yrs 1day COE left)

Mileage 78,117 km (13k /yr)

Manufactured ② 2016

Road Tax ① \$1,212 /yr

Transmission Auto

Dereg Value ② \$60,161 as of today (change)

OMV ② \$45,440

COE ② \$53,001

ARF ② \$55,616

Engine Cap 1,999 cc

Power 177.0 kW (237 bhp)

Curb Weight ② 1,841 kg

No. of Owners ② 2