

Section A - Accident Details

Registration Number	SHB699D
Case Reference Number	TAX/11/22/2020
Registration Date	14/1/2015
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SU LAK KIONG
Type of Accident	Side Swipe
Accident Date and Time	13/11/2022 11:08 AM
Accident Reported Date and Time	14/11/2022 8:38 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116855, 24117320
Special Instruction to ARC, if any	FRONT LEFT PORTION
Prepared Date and Time	14/11/2022 1:02 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$5,956.45	\$1,483.95
Total Other Cost	\$380.00	(\$383.95)
TOTAL COST	\$7,750.45	\$1,500.00 - \$500.00 (REPAIR COST EXCEED SALVAGE VALUE BEARED BY STRIDES TAXI) = \$1,000.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / AXA
ARC / Surveyor Sign Off Date	17/11/2022 10:07 AM	14/11/2022 4:37 PM
Signature		
Remarks	REQ NBV / Lumpsum repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0029, QN-2301-0039	Invoice Number	
Quotation Date	07.12.2022, 05.01.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$200.00 ✓
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$738.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$383.95)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	(\$383.95)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$602.60	30.00	\$421.82	Replace	Replace
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	30.00	\$33.60	Replace	Replace
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$97.60	0.00	\$0.00	Replace	Check
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$567.90	0.00	\$0.00	Replace	Check
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$284.00	0.00	\$0.00	Replace	Not Given
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$284.00	0.00	\$0.00	Replace	Not Given
		52114-47140	BRACKET, FR BUMPER	1.00	\$126.10	30.00	\$88.27	Replace	Replace
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace
		52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$21.40	30.00	\$14.98	Replace	Replace
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	1.00	\$389.90	30.00	\$272.93	Replace	Replace
		81220-12230	FOG LAMP LH	0.00	\$319.30	0.00	\$0.00	Replace	Not Given

✓ CRA
 ✓ NEC
 X
 X X NN
 X
 X
 ✓ CRA
 ✓ BT
 ✓ BT
 ✓ MIS
 ✓ CRA
 X X NN

