MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 6748 4422 / 6745 4422 Fax: 6747- 6720 REG NO 200501102H

LONPAC INSURANCE BHD			Quotation
300 Beach Road #17-04/07	Xias Tong.		: 10.11.2022
The Concourse	<u>o</u>		: SNE2056J
Singapore 199555			: Toyota Harrier
Tel: 6250 - 7388			: 05.11.2022
Fax: 6296 - 2706		YR REF	: GBD5393M

Attn: Motor Claim Dept

(Pls arrange vehicle surveyor & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SNE2056J (TOYOTA HARRIER)

<u>Item</u>	Description		Qty	Δ	<u>mt</u>	
NO	LIST ITEMS					
1 2 3 4 5 6 7 8	Front Bumper Side Hor Front Fender - LH Front Fender 'Hybrid' Front Door - LH Front Door Outer Har Front Door Wing Mirrort Door Wing Mirrort Door Wing Mirrort	Deuted Emblem - LH Hu idle - LH Ut or - LH Dund		1 1 1 1 1 1 1	3301.60 2476.20	676.60 48.40 1,360.60 56.00 1,905.40 478.70 29.5 1,735.90 105.50
	S/NETT ITEMS		Less 25%		\$	6,367.10 (1,591.78) 4,775.33
1	Front Bumper Clips	the new		1 set		30.00 ×
			Total Parts		\$	4,805.33
	LABOUR CHARGE					
1	To knocking & pull or	ut front LH portion &	renew above pa	arts	\$	800.00 500
2	To putty & spray up	paint works			\$	900.00 700
3	To check wiring syst	em			\$	900.00 700 50,00 30 150.00 40
4	To spray tuff coat				\$	150.00 40

RE: ESTIMATE FOR ACCIDENT REPAIR SNE2056J (TOYOTA HARRIER)

Total Labour \$ 2,050.00

Grand Total \$ 6,855.33

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 3746.20 4/s: 3k. OHDays,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: