

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

DATE : 09.11.2022

TO : CTP MOTOR CLAIMS DEPTS
VEHICLE NO : GBL 2314 U
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 01.11.2022
CHASSIS : KDY2318047255
DATE OF REG : 31.03.2021

Xiao Tong

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE HOLDER <i>new</i>	1	\$ 196.70	\$ 196.70
2	TAIL LAMP <i>new</i>	2	\$ 245.30	\$ 490.60
3	TAIL LAMP BASE <i>new</i>	2	\$ 175.80	\$ 351.60
4	REAR REFLECTOR <i>new</i>	2	\$ 42.50	\$ 85.00
5	REAR EXHAUST <i>new</i>	1	\$ 896.70	\$ 896.70
TOTAL PRICE				\$ 2,020.60
LESS 25%				\$ 505.15
SUB TOTAL PRICE				\$ 1,515.45

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR NUMBER PLATE LAMP <i>new</i>	1	\$ 75.00	\$ 75.00
3	REAR BOX OPEN DOOR (SPECIAL TYPE) (COMPLETE SET) <i>new</i>	2	\$ 2,800.00	\$ 5,600.00
4	REAR BOX OPEN DOOR HINGE (SPECIAL TYPE) <i>new</i>	4	\$ 95.00	\$ 380.00
5	REAR BOX OPEN DOOR LOCK CATCH (SPECIAL TYPE) <i>new</i>	2	\$ 120.00	\$ 240.00
6	REAR BOX OPEN DOOR LOCK <i>new</i>	2	\$ 250.00	\$ 500.00
7	REAR BOX OPEN DOOR '70KM/H' <i>new</i>	1	\$ 20.00	\$ 20.00
8	REAR SAFETY BAR (SPECIAL TYPE) <i>new</i>	1	\$ 1,200.00	\$ 1,200.00
9	REAR PROTECTOR BAR RUBBER (SPECIAL TYPE) <i>new</i>	2	\$ 250.00	\$ 500.00
10	REAR BOX OPEN DOOR FRAME (STANDARD STEEL) (SPECIAL TYPE) <i>new</i>	1	\$ 4,500.00	\$ 4,500.00
11	REAR CARGO BED ALUMINIUM CHASSIS <i>new</i>	1	\$ 3,000.00	\$ 3,000.00

Reverse Sensor
new

300.
200.

TOTAL \$ 16,065.00

3885

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

TO : CTP MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL 2314 U
 MODEL : TOYOTA DYNA
 DATE OF ACCIDENT : 01.11.2022
 CHASSIS : KDY2318047255

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,400.00	600
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,400.00	250
3	TO LIFT UP CARGO TO CHANGE REAR CHASSIS MMBER	\$ 800.00	200
4	TRANSFER REAR DOOR MECHANISM	\$ 380.00	80
5	REAR CHASSIS ALIGHMENT	\$ 250.00	x
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,410.00

TOTAL PARTS COST : \$ 17,580.45
 TOTAL LABOUR COST : \$ 4,410.00
 TOTAL REPAIR COST : \$ 21,990.45

Adrian Cj

h/s 10/11/22.

06 Days.

h/s: 5015

h/s: 4K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4.10