



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2304071

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 23/06/2023
Reference CC6/CTI22011424/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBL 2314U
Insured Veh. GZ 8458R
Claim No. SNM22D207925/C02
Policy No. DMCVSNW00101602200
Accident Date 01/11/2022
Inspection Date 10/11/2022

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (8%)	22.40
Grand Total	302.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22011424/Apa3q2 Date: 23/06/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 8458R	Veh. Inspected	GBL 2314U	
Policy No.	DMCVSNW00101602200	Coverage (\$)	0.00	
Claim No.	SNM22D207925/C02	Excess (\$)	0.00	
Assign From		Assign Date	10/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	KDY2318047255	Colour	WHITE	
Odometer	63667 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	TRIANGLE	6 mm	
L/H Front Tyre	195 R15C	TRIANGLE	6 mm	
R/H Rear Tyre	155 R12C	BRIDGESTONE	6 mm	
L/H Rear Tyre	155 R12C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/11/2022	Inspection Date	10/11/2022	
Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 2314U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR NUMBER PLATE HOLDER	NOT NECESSARY	196.70	-
2	TAIL LAMP @\$245.30	NOT NECESSARY	490.60	-
2	TAIL LAMP BASE @\$175.80	NOT NECESSARY	351.60	-
2	REAR REFLECTOR @\$42.50	NOT NECESSARY	85.00	-
1	REAR EXHAUST	NOT NECESSARY	896.70	-
	LESS 25% DISCOUNT		-505.15	-
			1,515.45	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE LAMP (SN)	NOT NECESSARY	75.00	-
2	REAR BOX OPEN DOOR (SPECIAL TYPE) (COMPLETE SET) @\$2800.00 (SN)	N/S CRACKED	5,600.00	2,200.00
4	REAR BOX OPEN DOOR HINGE (SPECIAL TYPE) @\$95.00 (SN)	BENT	380.00	95.00
2	REAR BOX OPEN DOOR LOCK CATCH (SPECIAL TYPE) @\$120.00 (SN)	DAMAGED	240.00	80.00
2	REAR BOX OPEN DOOR LOCK @\$250.00 (SN)	DAMAGED	500.00	200.00
1	REAR BOX OPEN DOOR '70KM/H' (SN)	NECESSARY	20.00	10.00
1	REAR SAFETY BAR (SPECIAL TYPE) (SN)	NOT NECESSARY	1,200.00	-
2	REAR PROTECTOR BAR RUBBER (SPECIAL TYPE) @\$250.00 (SN)	CRUSHED	500.00	200.00
1	REAR BOX OPEN DOOR FRAME (STANDARD STEEL) (SPECIAL TYPE) (SN)	DENTED	4,500.00	900.00
1	REAR CARGO BED ALUMINIUM CHASSIS (SN)	TO REPAIR SEE LABOUR	3,000.00	-
1	REVERSE SENSOR (SN)	DAMAGED	300.00	200.00
			16,365.00	3,885.00
	<u>LABOUR</u>			
	TO PANEL BEAT, WELD ,CUT ,ADJUST ,KNOCK.INCLUSIVCE OF THE REPAIR OF REAR CARGO BED ALUMINIUM CHASSIS .		1,400.00	600.00
	TO PUTTY ,SPRAY PAINT,POLISH WAX.		1,400.00	250.00

Report Ref No. CC6/CTI22011424/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LIFT UP CARGO TO CHANGE REAR CHASSIS MEMBER .		800.00	200.00
	TRANSFER REAR DOOR MECHANISM .		380.00	80.00
	REAR CHASSIS ALIGHMENT .	NOT NECESSARY	250.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			4,410.00	1,130.00
GRAND TOTAL			22,290.45	5,015.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CC6/CTI22011424/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 2314U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 2314U

RE-INSPECTION

