

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22011431/AQCE2**Date:** 03/05/2023**REFERENCE**

Insured/Claimant:	YONG WAI CHENG	Policy No:	7220118108	
Date of Loss:	09/11/2022	Nature of Claim:	OD	Claim No: 5483850190SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFC6767U	Engine No:	DKY016531
Make & Model:	AUDI A6 DESIGN, 2.0 TFSI (140 KW) (A)	Chassis No:	WAUZZZF2XNN018264
Reg. Date:	26/10/2022 (Man. Year: 2021)	Odometer:	638 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$290,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,405.00	4,293.20	3,111.80	42.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,172.00	2,822.00	2,350.00	45.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,577.00	7,115.20	5,461.80	43.43
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	11,977.00	6,515.20	5,461.80	45.60
+ GST 8.00/8.00% (\$\$)	958.16	521.22	436.94	45.60
Nett Amount (\$\$)	12,935.16	7,036.42	5,898.74	45.60

INSPECTION

Date of Assignment:	15/11/2022		
Date Inspected:	14/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EXTERIOR WING MIRROR MOUNTING - LH	Cut	3,069.00 FS	*2,455.20 FS
2	1		*FRONT WING MIRROR CAP - LH	Cracked	348.00 FS	*278.00 FS
3	1		*FRONT WING MIRROR GLASS - LH	Cracked	1,298.00 FS	*1,038.40 FS
4	1		*FRONT DOOR HANDLE - LH	Repair	389.00 FS	*- FS
5	1		*FRONT DOOR HANDLE CHROME TRIM PLATE - LH	Not Necessary	109.00 FS	*- FS
6	1		*FRONT DOOR PANEL CHROME CAP - LH UPPER	Not Necessary	100.00 FS	*- FS
7	1		*FRONT WINDOW GUIDE TRIM STRIP - LH	Cut	287.00 FS	*229.60 FS
8	1		*FRONT WINDOW GUIDE - LH	Not Necessary	542.00 FS	*- FS
9	1		*FRONT DOOR WINDOW - LH	Cut	365.00 FS	*292.00 FS
10	1		*REAR DOOR HANDLE - LH	Repair	389.00 FS	*- FS
11	1		*REAR DOOR HANDLE CHROME TRIM PLATE - LH	Not Necessary	109.00 FS	*- FS
12	1		*REAR DOOR PANEL CHROME CAP - LH UPPER	Not Necessary	100.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	7,405.00 4,293.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE OF LHS FRONT DOOR	New	280.00	280.00
2	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS	New	400.00	400.00
3	TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	800.00	500.00
4	TO RESPRAY LHS WING MIRROR COVER, LHS FRONT DOOR, LHS REAR DOOR, TWO DOOR HANDLES AND LHS REAR FENDER	New	3,500.00	1,450.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,172.00	2,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >