

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0993/2022/EQ
DATE : 11-Nov-22
WIP : 50316

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS YONG WAI CHENG
ADDRESS : 8 DOVER RISE
#20-03
SINGAPORE 138679
TELEPHONE : HP +65 81280836
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220118108
VEHICLE NO : **SFC 6767 U**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 26/10/2022
ENGINE NO : DKY 016531
CHASSIS NO : WAUZZZF2XNN018264
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Nov-22
PLACE OF ACCIDENT : DUNEARN ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Xiao Chan

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFC 6767 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE OF LHS FRONT DOOR.	S/N \$	280.00	✓
(2)	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS.	S/N \$	400.00	✗ ✓ <i>sls</i>
3	TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	800.00	<i>500</i> ✓
4	TO RESPRAY LHS WING MIRROR COVER, LHS FRONT DOOR, LHS REAR DOOR, TWO DOOR HANDLES AND LHS REAR FENDER.	\$	3,500.00	<i>1450</i> ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 5,172.00</u>	

*Mirror : 150
Handle x 2 : 200
Door 550
Fender 550
1450*

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFC 6767 U

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT EXTERIOR WING MIRROR MOUNTING - LH <i>cut</i>	1	\$ 2455.70	3,069.00 ✓ <i>sls</i>
2	FRONT WING MIRROR CAP - LH <i>cracked</i>	1	\$ 278	348.00 ✓ <i>sls</i>
3	FRONT WING MIRROR GLASS - LH <i>cracked</i>	1	\$	1,298.00 ✓ <i>1038.40</i>
4	FRONT DOOR HANDLE - LH <i>Regis</i>	1	\$	389.00 +
5	FRONT DOOR HANDLE CHROME TRIM PLATE - LH <i>new</i>	1	\$	109.00 +
6	FRONT DOOR PANEL CHROME CAP - LH UPPER	1	\$	100.00 +
7	FRONT WINDOW GUIDE TRIM STRIP - LH <i>cut</i>	1	\$	287.00 ✓ <i>229.60</i>
8	FRONT WINDOW GUIDE - LH <i>new</i>	1	\$	542.00 +
9	FRONT DOOR WINDOW - LH <i>cut</i>	1	\$ 297	365.00 ✓ <i>sls</i>
10	REAR DOOR HANDLE - LH <i>Regis</i>	1	\$	389.00 +
11	REAR DOOR HANDLE CHROME TRIM PLATE - LH <i>new</i>	1	\$	109.00 +
12	REAR DOOR PANEL CHROME CAP - LH UPPER <i>new</i>	1	\$	100.00 +
13	SUNDRIES <i>Not Nec.</i>		\$	300.00 ? X
TOTAL SPARE PARTS		:	\$	7,405.00
TOTAL LABOUR CHARGES		:	\$	5,172.00
GRAND TOTAL		:	\$	12,577.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian G
Resurveyed
sls

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian G

SURVEYED DATE

:

14/11/22

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 05 days.

S.S.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT