

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG20004176/EA3Q2-2**Date:** 25/11/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GV657G**Insured Vehicle No :** GW5402L

Date of Loss: 06/03/2020

Nature of Claim: TP

Claim No: 6541913643SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GV657G**

Make & Model: MITSUBISHI L300, 1.6 (M)

Engine No: 4D56KG1306

Reg. Date: 30/10/2001 (Man. Year: 2001)

Chassis No: JMAJNP15VYA001512

Colour: Beige

Odometer: 385265 km

Engine Capacity: 2477 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14C

Rear Tyre Size: 185 R14C

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		1,248.00		
Nett Amount (S\$)	0.00	1,248.00	-1,248.00	
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,895.45		
Global Sum Settlement (S\$)		1,730.00		

INSPECTION

Date of Assignment: 18/03/2020

Date Inspected: 18/03/2020 Inspected At:

My Car Consultant Pte Ltd
60 Jalan Lam Huat, Carros Centre #05-67/68
S(737869)

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE**Manager:** HOW MEI KWAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$6,500.00

LTA REIMBURSEMENT VALUE (RV) : \$5,252.00

NETT VALUE : \$1,248.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >