

Date: 14/11/2022

Vehicle No: SNC2667G

Model: MAZDA 3 SEDAN 1.5L

Chassis: JM6BM42A8G0944631-2016

Reg.Year: 2016

Third Party Insurer: CHINA TAIPING

Third Party Veh No: SKN5612Y

Date of Accident: 14/11/2022

Estimator: TING AN

Surveyor:

Not Authorized
U/Sing @
Meeting After Rain
5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		<i>R</i> \$1,041.00
2	FRONT HEADLAMP LH	1		<i>R</i> \$3,500.00
3	FRONT HEADLAMP NOZZLE LH	1		\$250.00
4	FRONT HEADLAMP NOZZLE COVER LH	1		<i>R</i> \$100.00
5	FRONT BUMPER	1		<i>R</i> \$1,068.00
6	FRONT BUMPER SIDE BRACKET LH	1		<i>CM</i> \$55.00
7	FRONT BUMPER FOG LAMP COVER LH	1		<i>R</i> \$80.00
8	FRONT BUMPER FOG LAMP LH	1		<i>M</i> <i>R</i> \$270.00
9	FRONT GRILLE	1		<i>R</i> \$284.00
10	FRONT GRILLE CHROME MOULDING LH	1		\$434.00
11	FRONT UNIT CONVERTER	1		\$2,198.00
12	FRONT FENDER LH	1		<i>R</i> \$416.00
13	FRONT FENDER BRACKET LH	1		<i>R</i> \$70.00
14	FRONT FENDER INNER SHIELD LH	1		<i>CM</i> \$226.00
15	FRONT RIM LH	1		<i>R</i> \$1,160.00
16	FRONT ABSORBER LH	1		\$370.00
17	FRONT LOWER ARM LH	1		\$440.00
18	FRONT KNUCKLE ARM LH	1		\$680.00
19	FRONT WHEEL BEARING HUB LH	1		\$460.00
SUB TOTAL				\$13,102.00
LESS 20%				-\$2,620.40
PARTS TOTAL				\$10,481.60

X
✓
✓
✓
✓
✓
✓
✓
X
✓
✓
✓
✓
✓
✓
✓
✓
✓
✓

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1		<i>na</i> \$50.00
2	FRONT BUMPER CLIPS	1		<i>na</i> \$50.00
3	FRONT FENDER INNER SHIELD CLIPS LH	1		<i>na</i> \$40.00
4	FRONT TYRE LH	1		\$250.00
S/N TOTAL				\$390.00

X
✓
✓
✓

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 14/11/2022
Vehicle No: SNC2667G
Model: MAZDA 3 SEDAN 1.5L
Chassis: JM6BM42A8G0944631-2016
Reg.Year: 2016

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SKN5612Y
Date of Accident: 14/11/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

500
\$800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & ETC.

700
\$800.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER LH, FRONT LOWER ARM LH, FRONT KNUCKLE ARM LH, FRONT WHEEL BEARING LH & ETC.

350
\$350.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT RIM LH.

120
\$120.00

TO WHEEL ALIGNMENT & BALANCING.

80
\$80.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

150
\$150.00

TO CHECK WIRING & ELECTRICAL SYSTEM.

80
\$80.00

LABOUR TOTAL \$2,380.00

TING AN TOTAL \$13,251.60

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

