

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22011441/TNY3Q2**Date:** 28/12/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000922	
Claimant Vehicle No :	SHC1931X	Insured Vehicle No :	SNC4724L	
Date of Loss:	12/11/2022	Nature of Claim:	TP	Claim No: M2206406

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1931X	Engine No:	G4LEJU110361
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVKU146338
Reg. Date:	14/05/2019 (Man. Year: 2019)	Odometer:	483503 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,514.12	4,514.12	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,315.00	1,705.00	610.00	26.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,840.12	6,230.12	610.00	8.92
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	6,840.12	5,000.00	1,840.12	26.90
+ GST 7.00/7.00% (S\$)	478.81	350.00	128.81	26.90
Nett Amount (S\$)	7,318.93	5,350.00	1,968.93	26.90

INSPECTION

Date of Assignment:	14/11/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	15/11/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1931X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	588.80 FL	*588.80 FL
2	1		*FRONT FENDER EMBLEM RH	Necessary	26.60 FL	*26.60 FL
3	1		*FRONT DOOR PANEL RH	Bent	1,797.20 FL	*1,797.20 FL
4	1		*REAR DOOR PANEL RH	Bent	1,789.90 FL	*1,789.90 FL
5	1		*ROCKER GARNIH PANEL RH	Deformed	290.00 FL	*290.00 FL
6	1		*FRONT DOOR PROTECTOR RH	Deformed	110.00 FL	*110.00 FL
7	1		*REAR DOOR PROTECTOR RH	Deformed	125.00 FL	*125.00 FL
8	1		*FRONT WHEEL CAP RH	Cut	346.40 FL	*346.40 FL
9	1		*FRONT FENDER ADVERTISEMENT	Cut	100.00 FS	*100.00 FS
10	1		*FRONT DOOR ADVERTISEMENT	Cut	100.00 FS	*100.00 FS
11	1		*REAR DOOR ADVERTISEMENT	Cut	100.00 FS	*100.00 FS
12	1		*REAR DOOR COMFORT APP	Necessary	80.00 FS	*80.00 FS
13	1		*FRONT DOOR COMFORT STICKER	Necessary	75.00 FS	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,528.90	5,528.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,014.78	1,014.78
Total Parts (\$\$)	4,514.12	4,514.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	875.00	525.00
2	SPRAY PAINTING	New	1,200.00	1,000.00
3	REMOVE/REFIX DOOR PART (FRONT /REAR)	New	180.00	120.00
4	RESET WHEEL ALIGNMENT	New	60.00	60.00
Gross Labour Cost (\$\$)			2,315.00	1,705.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >