

ASS. REC-BY: TaufikREF: CS/TM/22011441/Tay3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: _____ %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

wp

Date: _____

Person Contacted: Amay

Vehicle: IN / OUT

Veh No: SHC193/XYr Regn: 2019 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HyundaiC.C. 1580Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 483503

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH C85 / CVKM / 46338Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 15/11/22Survey held at Comfort LogisDes. of Damages: Fnt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/12/22 Taufikh confirmed lump sum: \$5000 and 3 days
(red, \$1840.12, 27%)

Date/Time, File Pass to?



: Preli. Report

1) 27/12/22



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

S + RS. SI. _____

Photos _____

Others _____

Add Fee: ☐

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

Report Format: TP

Lump Sum / L.B.H. / P

5000

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)59 Loyang Drive
Singapore 508969
Tel: 6214 8300**TP INSURER:** **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	12/11/2022
Vehicle Reg. No.:	SHC1931X	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	14/05/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU110361	Chassis No:	KMHC851CVKU146338
Odometer:	483503 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)**COST OF CLAIMS**

	Amount
Parts	4,514.12
Miscellaneous Items	11.00
Labour	2,315.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,840.12
+ GST 7.00% (S\$)	478.81
Nett Amount (S\$)	7,318.93

This claim is handled by: CHIANG LIAT CHOON

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Nov 2022)**Parts:** 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC1931X/14/11/2022 15:28**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER RH	20.00	0.00	bt *588.80 FL
2	1		*FRONT FENDER EMBLEM RH	20.00	0.00	na *26.60 FL
3	1		*FRONT DOOR PANEL RH	20.00	0.00	bt *1,797.20 FL
4	1		*REAR DOOR PANEL RH	20.00	0.00	bt *1,789.90 FL
5	1		*ROCKER GARNIH PANEL RH	20.00	0.00	de *290.00 FL
6	1		*FRONT DOOR PROTECTOR RH	20.00	0.00	dy *110.00 FL
7	1		*REAR DOOR PROTECTOR RH	20.00	0.00	de *125.00 FL
8	1		*FRONT WHEEL CAP RH	20.00	0.00	cut *346.40 FL
9	1		*FRONT FENDER ADVERTISEMENT	0	0.00	cut *100.00 FS
10	1		*FRONT DOOR ADVERTISEMENT	0	0.00	cut *100.00 FS
11	1		*REAR DOOR ADVERTISEMENT	0	0.00	cut *100.00 FS
12	1		*REAR DOOR COMFORT APP	0	0.00	na *80.00 FS
13	1		*FRONT DOOR COMFORT STICKER	0	0.00	na *75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,528.90
- List Item Discount on L Items (S\$)	1,014.78
Total Parts (S\$)	4,514.12

ComfortDelGro Engineering Pte Ltd/SHC1931X/14/11/2022 15:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

5073.90
20%-4059.12
SN 455

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
----	-----	-------------	--------

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
---	---	----------------------	-------

Sub Total (S\$)			11.00
-----------------	--	--	-------

11

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Labour Items

1	PANEL BEATING	New	525 875.00
2	SPRAY PAINTING	New	1000 1,200.00
3	REMOVE/REFIX DOOR PART (FRONT /REAR)	New	120 180.00
4	RESET WHEEL ALIGNMENT	New	60.00

Gross Labour Cost (S\$)			1705 2,315.00
-------------------------	--	--	---------------

ComfortDelGro Engineering Pte Ltd/SHC1931X/14/11/2022 15:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfer 97495749
 WP 15/11/22 @ 4:25pm
 c/s Resurvey after repair
 Tanfer C (Khan) - 4/585000
 03 days
 4059.12
 455
 11
 1705
 6230.12
 4/585000
 03 days
 *

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature.

Date:

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5230301

JC NO 305536459

CUSTOMER NAME: COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS: 383 SIN MING DRIVE Singapore SINGAPORE 575717 (F) 65508755 (O) (P) COUNT CARD NO.	REGN NO: SHC1931X	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G2) 14.11.2022 08:45	DATE/TIME IN
	YR OF MANU. 14.05.2019	TARGET DATE
	CHASSIS CODE KMHC851CVKU146338	COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 12.11.2022
NATURE: 3P 12.11.2022

:/NO

LABOR CODE

DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Edgeport Slip

Exit Pass

Vehicle No.: SHC1931X

CHIANG

Vehicle No.:

SHC1931X

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard