



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301933

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 28/03/2023  
Reference CC6/CTI22011442/Uya3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SNG 5765R  
Insured Veh. GBK 1251D  
Claim No. SNM22D208221/C02  
Policy No. DMCVSNW0002382201  
Accident Date 13/11/2022  
Inspection Date 15/11/2022

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (8%)</b>                | <b>32.00</b>  |
| <b>Grand Total</b>             | <b>432.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                           |                 |                                                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                           |                 | Ref: CC6/CTI22011442/Uya3q2<br>Date: 28/03/2023<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                 |                                                              |  |
| Insured Veh.                                                                                                                           | GBK 1251D                                                                                 | Veh. Inspected  | SNG 5765R                                                    |  |
| Policy No.                                                                                                                             | DMCVSNW0002382201                                                                         | Coverage (\$)   | 0.00                                                         |  |
| Claim No.                                                                                                                              | SNM22D208221/C02                                                                          | Excess (\$)     | 0.00                                                         |  |
| Assign From                                                                                                                            |                                                                                           | Assign Date     | 15/11/2022                                                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                 |                                                              |  |
| Make & Model                                                                                                                           | HYUNDAI TUCSON (A)                                                                        | c.c             | 1591                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.    | 2017                                                         |  |
| Chassis No.                                                                                                                            | KMHJ3812VHU445159                                                                         | Colour          | BLACK                                                        |  |
| Odometer                                                                                                                               | 98471 KM                                                                                  | Steering        | IN ORDER                                                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                  | Modification    | SPORTS RIM                                                   |  |
| General                                                                                                                                | GOOD                                                                                      |                 |                                                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                 |                                                              |  |
|                                                                                                                                        | Size                                                                                      | Make            | Balance                                                      |  |
| R/H Front Tyre                                                                                                                         | 245/45 R19                                                                                | DUNLOP          | 7 mm                                                         |  |
| L/H Front Tyre                                                                                                                         | 245/45 R19                                                                                | DUNLOP          | 7 mm                                                         |  |
| R/H Rear Tyre                                                                                                                          | 245/45 R19                                                                                | DUNLOP          | 7 mm                                                         |  |
| L/H Rear Tyre                                                                                                                          | 245/45 R19                                                                                | DUNLOP          | 7 mm                                                         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                 |                                                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                           |                 |                                                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                 |                                                              |  |
| Accident Date                                                                                                                          | 13/11/2022                                                                                | Inspection Date | 15/11/2022                                                   |  |
| Survey held at                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                 |                                                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                 |                                                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                 |                                                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                           |                 |                                                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                           | 3 Working Days  |                                                              |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 5765R

| Qty                                | Description of Parts                | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                     |                      |                           |                   |
| 1                                  | TAILGATE                            | TO REPAIR SEE LABOUR | 1,866.20                  | -                 |
| 1                                  | TAILGATE 'H' LOGO                   | NOT NECESSARY        | 39.90                     | -                 |
| 1                                  | TAILGATE 'TUCSON' EMBLEM            | NECESSARY            | 48.50                     | 48.50             |
| 1                                  | TAILGATE 'TURBO' EMBLEM             | NECESSARY            | 45.00                     | 45.00             |
| 1                                  | TAILGATE OUTER GARNISH              | DEFORMED / CRACKED   | 645.00                    | 428.00            |
| 2                                  | TAILGATE REFLECTORS @\$450.00       | NOT NECESSARY        | 900.00                    | -                 |
| 1                                  | TAILGATE INNER LOCK                 | NOT NECESSARY        | 188.90                    | -                 |
| 1                                  | TAILGATE WEATHERSTRIP               | NOT NECESSARY        | 299.20                    | -                 |
| 1                                  | REAR BUMPER                         | DEFORMED / TWISTED   | 845.20                    | 494.20            |
| 2                                  | REAR BUMPER REFLECTORS @\$105.00    | NOT NECESSARY        | 210.00                    | -                 |
| 1                                  | REAR BUMPER BEAM                    | CRACKED              | 516.80                    | 316.00            |
| 1                                  | REAR BUMPER LOWER GARNISH CENTRE    | DEFORMED / TWISTED   | 299.00                    | 299.00            |
| 1                                  | REAR BUMPER LOWER                   | DENTED               | 850.00                    | 415.00            |
| 2                                  | REAR BUMPER SIDE RETAINERS @\$65.00 | NECESSARY            | 130.00                    | 130.00            |
| 1                                  | SET REAR BUMPER CLIPS               | NECESSARY            | 45.00                     | 45.00             |
| 2                                  | TAILLAMPS @\$685.00                 | NOT NECESSARY        | 1,370.00                  | -                 |
| 1                                  | REAR END PANEL                      | TO REPAIR SEE LABOUR | 785.20                    | -                 |
| 1                                  | REAR END PANEL BUZZLE SENSOR        | NOT NECESSARY        | 250.00                    | -                 |
| 1                                  | REAR END PANEL TOP GARNISH          | NOT NECESSARY        | 199.00                    | -                 |
| 1                                  | REAR FLOOR PANEL                    | NOT NECESSARY        | 1,280.00                  | -                 |
| 1                                  | REAR FLOOR PANEL TOP BOARD          | NOT NECESSARY        | 615.00                    | -                 |
|                                    | LESS 20% DISCOUNT                   |                      | -                         | -444.14           |
|                                    |                                     |                      | 11,427.90                 | 1,776.56          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                     |                      |                           |                   |
| 1                                  | SET REAR BUMPER REVERSE SENSOR (SN) | SHORTED              | 280.00                    | 200.00            |
| 1                                  | REAR END PANEL SEALANT (SN)         | NOT NECESSARY        | 50.00                     | -                 |
| 1                                  | SET REAR BUMPER LOWER CHROME (SN)   | DENTED               | 800.00                    | 600.00            |

Report Ref No. CC6/CTI22011442/Uya3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                                                               | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                           | REAR LICENCE PLATE W/HOLDER (SN)                                                                   | SCRATCHED     | 50.00                     | 40.00             |
|                                                                             |                                                                                                    |               | 1,180.00                  | 840.00            |
|                                                                             | <b>LABOUR</b>                                                                                      |               |                           |                   |
|                                                                             | TO CHECK WIRING.                                                                                   |               | 50.00                     | 20.00             |
|                                                                             | TO DISMANTLE & REPLACED REVERSE SENSOR.                                                            |               | 80.00                     | 50.00             |
|                                                                             | TO TRANSFER BOOTLID MECHANISM.                                                                     | NOT NECESSARY | 100.00                    | -                 |
|                                                                             | TO DISMANTLE & REFIX CUSHION UPHOLSTERY.                                                           | NOT NECESSARY | 120.00                    | -                 |
|                                                                             | TO SPRAY RUST PROOFING.                                                                            | NOT NECESSARY | 100.00                    | -                 |
|                                                                             | TO RESET & REPROGRAMME SYSTEM.                                                                     | NOT NECESSARY | 180.00                    | -                 |
|                                                                             | LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL. |               | 1,800.00                  | 480.00            |
|                                                                             | TO PUTTY & SPRAY PAINTING.                                                                         |               | 1,800.00                  | 600.00            |
|                                                                             |                                                                                                    |               | 4,230.00                  | 1,150.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                    |               | <b>16,837.90</b>          | <b>3,766.56</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                    |               |                           | <b>3,000.00</b>   |

Report Ref No. CC6/CTI22011442/Uya3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SNG 5765R

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNG 5765R

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SNG 5765R

### RE-INSPECTION

