

Shiau Chan (LKKAuto)

**From:** Tan Alan <atautoconsultant@gmail.com>  
**Sent:** Wednesday, 4 January 2023 7:07 PM  
**To:** Finalization  
**Cc:** Shiau Chan (LKKAuto); SUR  
**Subject:** Re: PC216P--Check Item, After Paint & Sup Estimate \*\*\* LKK REF: CS/CTI22011445/Eqy3

Hi,

Thank you for your reply, please advise if the COR is confirm.

Rgds  
Alan

On Wed, Jan 4, 2023, 19:02 Finalization <[finalization@lkkauto.com](mailto:finalization@lkkauto.com)> wrote:  
Hi Alan,

We will be advising our principal for the costs of repairs in \$19,950.00 (L/S, before GST), 12 days. Subject to their approval.

Thank you.  
Best Regards,

**LKK Auto Consultants Pte Ltd**  
Phone: 6366 0055 |  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan Alan <[atautoconsultant@gmail.com](mailto:atautoconsultant@gmail.com)>  
**Sent:** Tuesday, 3 January 2023 5:53 PM  
**To:** Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>  
**Subject:** Fwd: PC216P--Check Item, After Paint & Sup Estimate

Hi Mei Kwan,

I understand Steve has left LKK, please help me with this case, thank you.

Rgds  
Alan

----- Forwarded message -----  
From: **Tan Alan** <[atautoconsultant@gmail.com](mailto:atautoconsultant@gmail.com)>  
Date: Fri, Dec 9, 2022 at 5:28 PM  
Subject: PC216P--Check Item, After Paint & Sup Estimate  
To: <[stevechen@lkkauto.com](mailto:stevechen@lkkauto.com)>

Hi Steve,

Attached are the above-mentioned items, thank you.

\*\*Please relook into the LH fender compensation as it was found cracked after we dismantled the rear bumper.  
\*\*Attached is a sup estimate for the rear bumper number plate LED lamp.  
\*\*\*\* Photos supported in the check item for both above-mentioned items.

Thank you.

--  
Rgds  
Alan Tan  
83868989  
A T Auto Consultant

--

Rgds  
Alan Tan  
83868989  
A T Auto Consultant