

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011448/RNY3M4**Date:** 10/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00220012101

**Claimant Vehicle No :** FBN7601Y **Insured Vehicle No :** SKW7046X

Date of Loss: 28/10/2022 Nature of Claim: TP Claim No: SNM22D207804/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **FBN7601Y**

Make & Model: BMW R1200GS, 1.2 (M) Engine No: 122EN25150172

Reg. Date: 11/12/2015 (Man. Year: 2015) Chassis No: WB10A0100FZ171439

Colour: Multi-colour Odometer: 43261 km

Engine Capacity: 1170 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 120/70ZR19 Rear Tyre Size: 170/60ZR17

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,391.00	5,034.50	356.50	6.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	300.00	150.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,841.00</b>	<b>5,334.50</b>	<b>506.50</b>	<b>8.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,250.00</b>		
<b>(S\$)</b>	5,841.00	4,250.00	1,591.00	27.24
<b>+ GST 8.00/8.00% (S\$)</b>	467.28	340.00	127.28	27.24
<b>Nett Amount (S\$)</b>	<b>6,308.28</b>	<b>4,590.00</b>	<b>1,718.28</b>	<b>27.24</b>

**INSPECTION**

Date of Assignment: 15/11/2022

Date Inspected: 16/11/2022 Inspected At: SOUTHERN MOTOR  
BLOCK 1006 BUKIT MERAH LANE 2  
#01-10 SINGAPORE 159762

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Jan 2023)	
Parts:	N/A	BMW R1200GS 1.2 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN7601Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR SIDE BOX	Deformed	2,500.00 FL	*2,500.00 FL
2	1		*REAR BOX	Scratched	1,680.00 FL	*1,680.00 FL
3	1		*REAR MUDGUARD	Cracked	320.00 FL	*320.00 FL
4	1		*ENGINE GUARD LH	Scratched	580.00 FL	*580.00 FL
5	1		*TANK COVER	Cracked	190.00 FL	*190.00 FL
6	1		*HANDLE BAR	Not Necessary	385.00 FL	*- FL
7	1		*HANDLE GUARD	Scratched	285.00 FL	*285.00 FL
8	1		*NUMBER PLATE	Bent	45.00 FS	*35.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					5,985.00	5,590.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					594.00	555.50
Total Parts (\$\$)					5,391.00	5,034.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR	New	450.00	300.00
<b>Gross Labour Cost (\$\$)</b>			<b>450.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >