



南方摩哆

Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

11-Nov-22

China Taiping Insurance Singapore Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore (079909)

Dear Sirs,

lump sum: \$4250

4999.50
342.45
5341.95

RE: Cost of repair to BMW R1200GS - FBN7601Y

2 pcs of Rear Side Box <i>de</i>	SS	2,500.00
1pc of Rear Box <i>sur</i>		1,680.00
1pc of Rear Mudguard <i>cra</i>		320.00
1pc of Engine Guard LH <i>sc</i>		580.00
1pc of Tank Cover <i>cra</i>		190.00
1pc of Handle Bar <i>? X m</i>		385.00 X
1pc of Handle Guard <i>sc</i>		285.00
	5555	<u>5,940.00</u>
Less 10%	10%	594.00
Nett	4999.50	<u>5,346.00</u>
LTA Fees		7.45
Number Plate	342.45	<u>45.00</u> 35
Labour		<u>450.00</u> 300
		<u>\$5,848.45</u>



Yours Faithfully,
Southern Motor

Rare
Hp 90010068

3 days

4/5 or P/P?

Resy before or after
repair
16/11/22 @ 1000

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: