



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22011449/Dqy3e2 Date: 27/02/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBK 7131C	Veh. Inspected	SJW 1077H
Policy No.	D-22098775MFCV/132	Coverage (\$)	0.00
Claim No.	D22003573MFCV	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	14/11/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C180K	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2040452A356180	Colour	SILVER
Odometer	142112 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	BRIDGESTONE	5 mm
L/H Front Tyre	225/45 R17	BRIDGESTONE	5 mm
R/H Rear Tyre	225/45 R17	BRIDGESTONE	5 mm
L/H Rear Tyre	225/45 R17	BRIDGESTONE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/11/2022	Inspection Date	21/11/2022
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	