

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011452/EVY3M4**Date:** 15/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00115842202
Claimant Vehicle No :	SMJ778H	Insured Vehicle No :	XD8106X
Date of Loss:	12/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208186/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ778H		
Make & Model:	MERCEDES-BENZ GLA200, 1.6 (A)	Engine No:	27091031734046
Reg. Date:	01/03/2019 (Man. Year: 2018)	Chassis No:	WDC1569432J545211
Colour:	Black	Odometer:	38672 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,925.00	4,212.00	3,713.00	46.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,650.00	1,300.00	44.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,875.00	5,862.00	5,013.00	46.10
+ GST 7.00/7.00% (S\$)	761.25	410.34	350.91	46.10
Nett Amount (S\$)	11,636.25	6,272.34	5,363.91	46.10

INSPECTION

Date of Assignment:	17/11/2022	
Date Inspected:	15/11/2022	Inspected At:
Estimated Period of Repair:	4.0 days	

AUTOSPRINT PTE LTD
24 LENG KEE ROAD
#07-01/02 LENG KEE AUTOPOINT
SINGAPORE 159096

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2022)
Parts:	M1-SUV	MERCEDES-BENZ GLA200 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ778H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,440.00 F	*1,440.00 FL
2	2		*FRONT BONNET HINGES	Bent	210.00 F	*210.00 FL
3	1		*FRONT BUMPER	Dented	2,000.00 F	*1,625.00 FL
4	1		*FRONT BUMPER RETAINERS & RIVETS	Necessary	100.00 F	*80.00 FL
5	1		*FRONT GRILLE ASSY	Broken	860.00 F	*860.00 FL
6	1		*FRONT TOP PANEL	Not Necessary	450.00 F	*- FL
7	1		*FRONT TOP PANEL RUBBER	Not Necessary	240.00 F	*- FL
8	1		*L/H FRONT HEAD LAMP	Not Necessary	2,160.00 F	*- FL
9	1		*FRONT BUMPER MOUNTING	Broken	195.00 F	*195.00 FL
10	1		*FRONT STAR LOGO	Necessary	110.00 F	*110.00 FL
11	2		*FRONT AIR FLOW DEFLECTORS	Broken	160.00 F	*160.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,925.00	4,680.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	468.00
Total Parts (\$\$)	7,925.00	4,212.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO STRAIGHTEN FRONT PANEL, REPLACE THE ABOVE LISTED DAMAGED PARTS	New	1,500.00	550.00
2	LABOUR CHARGE TO SPRAY PAINTING SAME	New	1,000.00	900.00
3	LABOUR CHARGE TO RECONNECT FRONT WIRE HARDNESS, TO PROGRAMMING & CODING INFOTAINMENT SYSTEM	New	450.00	200.00
Gross Labour Cost (S\$)			2,950.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >