

UEN No. 201729594D

AUTOSPRINT PTE LTD 24 Leng Kee Road #07-02B/C/D Leng Kee AutoPoint Singapore 159096 Tel: 6911 8338 Fax: 6251 7438 Email. enquiry@autosprint.com.sg

QUOTATION

To: Gary See Gim Boon SMJ778H, MERCEDES BENZ, GLA200 AMG LINE AUTO

Our Ref: Q221104 Date :14 Nov 2022

Attn : Gary See Gim Boon (9017 8843)

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Rem	arks :T/Party Claims			(54)	Amt (S\$)
No.	Description	Qty	UOM	U/P (S\$)	Amt (5\$)
	Ad hoc				1,440.00 🗸
	Front Bonnet / 00	1.00		1,440.00	210.00 🗸
	Front Bonnet Hinges / NT	2.00		105.00	2,000.00 162
	Front Bumper / M	1.00		2,000.00	
	Front Bumper Retainers & Rivets / //	1.00		100.00 41	860.00 🗸
	Front Grille Assy / 1/k	1.00		860.00	450.00 ×
	Front Top Panel 🗴 nn	1.00		450.00	240.00×
	Front Top Panel Rubber X nn	1.00		240.00	2,160.00
	L/H Front Head Lamp // X nn	1.00		2,160.00	
	Labour Charge to straighten front panel, replace the	1.00	550 V	1,500.00	1,500.00
	above listed damaged parts		900 V	1,000.00	1.000.00
0	Labour Charge to spray painting same () food () food	1.00		450.00	450.00
1	Labour Charge to reconnect front wire hardness, to	1.00	200 V	430.00	430.00
	programming & coding infotainment system				
	Stevechen @ IKK auto. com	parts	s - 4215	labour - 1650	
	STEWER WAY THE		-10%		-10
	Stove (LKK) 832288/3		3793.50		418
	Steve (LKK) 83228813				
	15/11/22, 5.30 pm		Т	otal - 5862.00	
	m IL				
	P / P	consulta	ants hence notify		
	the Repaire	er of the	following:	1	
	Red 18th Spy 1 o To resurvey		ter spray painting		
		play damaged part(s) during resurvey prices are subject to confirmation			
	4 de l'a Third party s	party survey is on a "Without Prejudice" basis			
			n(s) is allowed		
	□ Supplement	ntary item(s) must be resurveyed and			
	is subject to	final appr	roval from Insurance C	ompany	
	4 cknowledger	thy Pons	irer		
	ACAHAMOUJO				

Signature:

I have read and agree to the terms and conditions stated in the reverse side of this quotation and authorise AUTOSPRINT Pte Ltd to carry out the above work described. Additional quotation (if any) on subsequent repair found during inspection and diagnostics may be provided.

Subtotal: GST 7.0%: **Total Amount:** 10,410.00 10,875 728.70 11,138.70

PAGE 1 OF 1