

ASS. REC BY: Tau

REF:

CS/1112201459/7955

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / ☐ VS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 400

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 968K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLC773717 Yr Regn: 2016 MayType: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: BMW 3181 C.C. 1499Colour: white A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: _____ T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: WBA8E36050NT=89066Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 225/50R17R: 1BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ DHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm

D.O.A. _____ D.O.I. 6/11/22Survey held at Galaxy AutoDes. of Damages: ☒ Fty / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

(2)

Rep. Formet: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS \$ _____

Photos _____

GALAXY AUTO CARE PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-23 Singapore 417807

Tel: 9010 8488/ Email: claims8488galaxy@gmail.com

VEHICLE NO: SLC7737D

MAKE & MODEL: BMW 318I

DOA: 04.11.2022

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BONNET	1	\$ 1,825.00	RY
FRONT BONNET HINGE	2	\$ 170.00	X
FRONT BONNET LOCK LH	1	\$ 150.00	X
FRONT BONNET LOCK RH	1	\$ 150.00	X
FRONT BONNET LOCK CATCH	2	\$ 80.00	X
FRONT BONNET LOCK COVER	2	\$ 50.00	X
FRONT FENDER LH	1	\$ 920.00	X
FRONT FENDER INNER SHIELD LH	1	\$ 135.00	X
FRONT FENDER SUPPORT BRACKET LH	1	\$ 35.00	X
FRONT FENDER RH	1	\$ 920.00	X
FRONT FENDER INNER SHIELD RH	1	\$ 135.00	X
FRONT FENDER SUPPORT BRACKET RH	1	\$ 35.00	X
FRONT HEADLAMP ASSY LH	1	\$ 2,850.00	X
FRONT HEADLAMP ASSY RH	1	\$ 2,850.00	cur ✓
FRONT HEADLAMP CONTROL UNIT LH	1	\$ 865.00	X
FRONT HEADLAMP CONTROL UNIT RH	1	\$ 865.00	?
FRONT HEADLAMP DRIVER MODULE LH	1	\$ 835.00	X
FRONT HEADLAMP DRIVER MODULE RH	1	\$ 835.00	X
FRONT HEADLAMP LED MODULE LH	1	\$ 205.00	X
FRONT HEADLAMP LED MODULE RH	1	\$ 205.00	X
FRONT HEADLAMP BULB LH	1	\$ 398.00	X
FRONT HEADLAMP BULB RH	1	\$ 398.00	X
FRONT HEADLAMP TOP BRACKET LH	1	\$ 59.00	X
FRONT HEADLAMP TOP BRACKET RH	1	\$ 59.00	cur ✓
FRONT HEADLAMP LOWER PANEL LH	1	\$ 65.00	X
FRONT HEADLAMP LOWER PANEL RH	1	\$ 65.00	X
FRONT BUMPER	1	\$ 1,390.00	dg ✓
FRONT BUMPER RETAINER LH	1	\$ 56.00	X
FRONT BUMPER RETAINER RH	1	\$ 56.00	?
FRONT BUMPER GRILLE LH	1	\$ 80.00	cur ✓
FRONT BUMPER GRILLE RH	1	\$ 80.00	cur ✓
FRONT BUMPER TOP SEAL	1	\$ 35.00	
FRONT BUMPER NOZZLE LH	1	\$ 90.00	X
FRONT BUMPER NOZZLE RH	1	\$ 90.00	?
FRONT BUMPER FOGLIGHT LH	1	\$ 265.00	X
FRONT BUMPER FOGLIGHT RH	1	\$ 265.00	X
FRONT BUMPER FOGLIGHT COVER LH	1	\$ 98.00	?
FRONT BUMPER FOGLIGHT COVER RH	1	\$ 98.00	?
FRONT BUMPER FOGLIGHT BRACKET LH	1	\$ 65.00	?
FRONT BUMPER FOGLIGHT BRACKET RH	1	\$ 65.00	?
FRONT BUMPER LOGO	1	\$ 85.00	na ✓
FRONT BUMPER CENTRE GRILLE	1	\$ 125.00	?
FRONT BUMPER REINFORCEMENT	1	\$ 831.00	?
FRONT BUMPER REINFORCEMENT BRACKET LH	1	\$ 75.00	?
FRONT BUMPER REINFORCEMENT BRACKET RH	1	\$ 75.00	?
FRONT BUMPER SPONGE	1	\$ 165.00	?
FRONT BUMPER LOWER BEAM	1	\$ 175.00	X

FRONT BUMPER LOWER BEAM BRACKET LH	1	\$ 65.00	✓
FRONT BUMPER LOWER BEAM BRACKET RH	1	\$ 65.00	✓
FRONT BUMPER LOWER BEAM BRACKET INNER LH	1	\$ 58.00	x
FRONT BUMPER LOWER BEAM BRACKET INNER RH	1	\$ 58.00	✓
AIR DUCT TOP	1	\$ 112.00	✓
AIR DUCT LOWER	1	\$ 112.00	✓
HORN	1	\$ 180.00	✓

\$ 20,073.00
 LESS 5% \$ 1,003.65
SUB TOTAL \$ 19,069.35

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT BONNET LOCK CATCH CLIPS	1 SET	\$ 50.00	x
FRONT BONNET SPONGE CLIPS	1 SET	\$ 50.00	x
FRONT FENDER INNER SHIELD CLIPS	2 SET	\$ 100.00	x
FRONT NUMBER PLATE W/GARNISH	1	\$ 90.00	de✓
HORN RIVETS	1 SET	\$ 50.00	x
JOINT SEALANT	1	\$ 120.00	✓
SUB TOTAL		<u>\$ 460.00</u>	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK FRONT WIRING AND LIGHTING SYSTEM	1	\$ 240.00	40
REMOVE AND REFIT FRONT LINING, TRIM AND GARNISH	1	\$ 150.00	x
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,800.00	400
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,800.00	450
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	x
SUB TOTAL		<u>\$ 4,090.00</u>	

GRAND TOTAL \$ 23,619.35

Tanfiki 97495749
 Not authorised Ex:tk
 L/R Resurvey after repair
 tanfiki@lkkauto.com
 4-5 days
 16/11/22 @ 3pm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: